

Date: 07/09/2022  
Vehicle No: SMR5275S  
Model: HYUNDAI IONIQ HEV 1.6  
Chassis: KMHC851CVLU200969 - 2019  
Reg.Year: 2020

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SLR2003S  
Date of Accident: 05/09/2022  
Estimator: KIT  
Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION       | QTY | UNIT S\$ | AMOUNT S\$ |
|-------------|-------------------|-----|----------|------------|
| 1           | REAR BUMPER       | 1   |          | REPAIR     |
| 2           | REAR FENDER RH    | 1   |          | REPAIR     |
| 3           | REAR RIM COVER RH | 1   |          | REPAIR     |
| SUB TOTAL   |                   |     |          | \$0.00     |
| LESS 20%    |                   |     |          | \$0.00     |
| PARTS TOTAL |                   |     |          | \$0.00     |

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$200.00 ✓

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$600.00 480

LABOUR TOTAL \$800.00

KIT TOTAL \$800.00

*Not Authen  
Pickup After Paint  
2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

