

Your Reference : DH0M120051812002  
Accident Date : 03-Sep-2022

No. : 32530

Date : 07-Sep-2022

Our Ref : 022255 / CARIN

PAGE : 1

CHENG KAM YIN (MR)  
C/O UNITED OVERSEAS INSURANCE LIMITED  
146 ROBINSON ROAD  
#02-01  
UOI BUILDING  
Singapore 068909

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6L CVT(2016) SLB9228Z  
=====

1 pc	front bumper		220.00	c
1 pc	o/s front bumper side retainer		40.00	c
10 pcs	front bumper clip	@ S\$ 1.50	15.00	c
1 pc	o/s front bumper foglamp		135.00	c
1 pc	o/s front bumper foglamp cover		90.00	c
1 pc	front bumper centre lower grille		85.00	c
1 pc	front bumper sponge		60.00	c
1 pc	o/s front fender		295.00	c
1 pc	o/s front fender 'VVTi' emblem		30.00	c
1 pc	o/s front fender inner shield		70.00	c
8 pcs	o/s front fender inner shield clip	@ S\$ 1.50	12.00	c
2 pcs	o/s front fender inner shield retainer clip	@ S\$ 6.00	12.00	c
2 pcs	o/s front fender inner shield retainer pin	@ S\$ 4.00	8.00	c
1 pc	wiper washer tank		80.00	c
1 pc	wiper washer tank motor		85.00	c
1 pc	o/s headlamp		650.00	c
1 pc	o/s headlamp top chrome		95.00	c
1 pc	engine front under cover		90.00	c
			-----	
			2,072.00	
	Add 10% :		207.20	
			-----	
				2,279.20

Con't Page 2 ...

Your Reference : DH0M120051812002  
Our Ref : 022255

Page : 2  
No. : 32530

To remove, cut out damaged parts,  
panel beating, welding, align, 680.00  
refix and to renew affected parts.

To conduct front wheel alignment 80.00  
test.

To putty and respray on affected 750.00  
portions.

To focus headlamps. To check front 30.00  
wiring and lighting operation.

Total : S\$ 3,819.20  
=====

Singapore Dollars Three Thousand Eight Hundred  
and Nineteen and Cents Twenty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.