

金興(興)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
160 Sin Ming Drive #02-18/19/20
Sin Ming AutoCity
Singapore 575722
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

KV

Your Reference : DH0M120051812002
Accident Date : 03-Sep-2022

No. : 32530

Date : 07-Sep-2022

Our Ref : 022255 / CARIN

PAGE : 1

CHENG KAM YIN (MR)
C/O UNITED OVERSEAS INSURANCE LIMITED
146 ROBINSON ROAD
#02-01
UOI BUILDING
Singapore 068909

NOT Authorized
U/Ry @ 2200h
Meaning After Paint
5days Ex @ 75cl

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6L CVT(2016) SLB9228Z

1 pc front bumper		Bucina	220.00	c	✓
1 pc o/s front bumper side retainer		NT	40.00	c	✓
10 pcs front bumper clip	@ S\$ 1.50	na	15.00	c	✓
1 pc o/s front bumper foglamp		na	135.00	c	✓
1 pc o/s front bumper foglamp cover		na	90.00	c	✓
1 pc front bumper centre lower grille		Roll up	85.00	c	✓
1 pc front bumper sponge		na	60.00	c	✓
1 pc o/s front fender		na	295.00	c	✓
1 pc o/s front fender 'VVTi' emblem		na	30.00	c	✓
1 pc o/s front fender inner shield		CM	70.00	c	✓
8 pcs o/s front fender inner shield clip	@ S\$ 1.50	na	12.00	c	✓
2 pcs o/s front fender inner shield retainer clip	@ S\$ 6.00	na	12.00	c	✓
2 pcs o/s front fender inner shield retainer pin	@ S\$ 4.00	na	8.00	c	✓
1 pc wiper washer tank		na	80.00	c	✓
1 pc wiper washer tank motor		na	85.00	c	✓
1 pc o/s headlamp		na	650.00	c	✓
1 pc o/s headlamp top chrome		na	95.00	c	✓
1 pc engine front under cover		na	90.00	c	✓
			2,072.00		
	Add 10% :		207.20		
			2,279.20		

Con't Page 2 ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DH0M120051812002
Our Ref : 022255

Page : 2
No. : 32530

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

680.00 *500*

To conduct front wheel alignment
test.

80.00 X

To putty and respray on affected
portions.

750.00 *600*

To focus headlamps. To check front
wiring and lighting operation.

30.00 *20*

Total : S\$ 3,819.20

Singapore Dollars Three Thousand Eight Hundred
and Nineteen and Cents Twenty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

1517.00
+ 10%

1668.70
+ 1120.00

2788.70
- 20%

2230.96

C/SUM \$2209.1