

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008790/ENY3Q2**Date:** 30/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00109652201

Claimant Vehicle No : SMA4655A **Insured Vehicle No :** SLC2437C

Date of Loss: 31/08/2022 Nature of Claim: TP Claim No: SNM22D206213/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA4655A**

Make & Model: MAZDA 6, 2.0 SEDAN EXECUTIVE EU6 (A) Engine No: PE21040398

Reg. Date: 08/01/2018 (Man. Year: 2017) Chassis No: JM6GL1071J0136889

Colour: Grey Odometer: 40182 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17

Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm

Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,864.00	424.00	1,440.00	77.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,160.00	650.00	35.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,674.00	1,584.00	2,090.00	56.89
+ GST 7.00/7.00% (\$\$)	257.18	110.88	146.30	56.89
Nett Amount (\$\$)	3,931.18	1,694.88	2,236.30	56.89

INSPECTION

Date of Assignment: 06/09/2022

Date Inspected: 07/09/2022 Inspected At: Ethoz Automotive Solutions Ltd (HQ)
30, BUKIT BATOK CRESCENT
Singapore 658075

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Nov 2022)

Parts: 143 MAZDA 6 2.0 SEDAN EXECUTIVE EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMA4655A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,040.00 FL	*- FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	46.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
4	1		*FRONT FENDER RH	Dented	390.00 FL	*390.00 FL
5	1		*FRONT FENDER INNERSHIELD RH	Not Necessary	138.00 FL	*- FL
6	10		*FRONT FENDER SHIELD CLIPS	Not Necessary	50.00 FL	*- FL
7	1		*WING MIRROR ASSY RH	Not Necessary	476.00 FL	*- FL
8	1		*WING MIRROR COVER RH	Missing	140.00 FL	*140.00 FL
9	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
10	1		*FRONT SPORTS RIM RH (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,330.00	530.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	466.00	106.00
Total Parts (\$\$)	1,864.00	424.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	800.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	900.00	650.00
3	TO CONDUCT WHEEL ALIGNMENT	New	80.00	80.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (\$\$)			1,810.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >