



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: FIONA SHEN			Ref: CS/INC22008795/Kqy3e2 Date: 28/12/2022 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 2812D	Veh. Inspected	SLR 7655C	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1183064-002	Excess (\$)	0.00	
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	07/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NSP1727001272	Colour	METALLIC PEARL WHITE	
Odometer	188274 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	GOFORM	9 mm	
L/H Front Tyre	185/60 R15	GOFORM	9 mm	
R/H Rear Tyre	185/60 R15	GOFORM	8 mm	
L/H Rear Tyre	185/60 R15	GOFORM	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/08/2022	Inspection Date	07/09/2022	
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	