

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7247T

Make : HYUNDAI

Model : IONIQ(G2)

Date: 09/05/22

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>X Repair</i>			\$ 459.40
10	REAR BUMPER CLIPS <i>X Repair</i>			\$ 22.00
1	REAR FENDER RH <i>X Repair</i>			\$ 1,768.30
1	REAR BUMPER SIDE BRACKET RH <i>X Repair</i>			\$ 55.80
SUB TOTAL				\$ 2,305.50
LESS 20%				\$ 461.10
DISCOUNTED TOTAL				\$ 1,844.40
REAR BUMPER RUBBER MAT <i>X Repair</i>				\$ 50.00
REAR DOOR COMFORT LOGO RH <i>X Repair</i>				\$ 80.00
NETT				\$ 130.00
Labour Charge				
PANEL BEATING				\$ 1,050.00
SPRAY PAINTING CHARGE				\$ 800.00
REMOVE/ REFIX REVERSE SENSOR				\$ 60.00
TUFF KOTE				\$ 60.00
REMOVE/ REFIX UPHOLSTERY & CUSHION RR				\$ 120.00
TOTAL LABOUR				\$ 2,090.00
ESTIMATE TOTAL				\$ 4,064.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.

L/S

Gue Qip

5/9/22

12pm

1180

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on "No Prejudice" basis
- No illegal modification to be made
- Supplemental survey on parts resurveyed and is subject to final determination by Insurance Company

Acknowledged by Repairer:

Signature:

Date: