

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III22007803/RCY3E2-1**Date:** 23/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_01

Claimant Vehicle No : SMQ414X **Insured Vehicle No :** SNC3352H

Date of Loss: 15/08/2022 Nature of Claim: TP Claim No: MFL2022D0004431

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ414X**

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 2NR5400394

Reg. Date: 29/10/2019 (Man. Year: 2019) Chassis No: MR2B23F3501191911

Colour: Grey Odometer: 56283 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,619.89	530.10	1,089.79	67.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	440.00	1,780.00	80.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,839.89	970.10	2,869.79	74.74
Approved Total (Overridden) (S\$)		750.00		
Nett Amount (S\$)	3,839.89	750.00	3,089.89	80.47

INSPECTION

Date of Assignment: 07/09/2022

Date Inspected: 17/08/2022 Inspected At:

Estimated Period of Repair: 3.0 days

Infinity Capital & Insurance (HQ)
39 WOODLANDS CLOSE, #01-08,
MEGA@WOODLANDS
Singapore 737856

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ414X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	492.00 FL	*492.00 FL
2	1		*REAR BUMPER SIDE HOLDER LH	Not Necessary	115.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repairable	318.90 FL	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
5	1		*REAR END PANEL	Repairable	602.10 FL	*- FL
6	1		*REAR TAIL LAMP LH	Not Necessary	322.90 FL	*- FL
7	1		*REAR FENDER OUTER GARNISH	Not Necessary	94.16 FL	*- FL
8	1		*REAR BUMPER REFLECTOR LH	Cracked	179.80 FL	*179.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,159.86	706.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	539.97	176.70
Total Parts (\$\$)	1,619.89	530.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT REAR END PANEL AND REAR LEFT FENDER. STRAIGHTEN REAR LEFT CHASSIS. REMOVE AND REPLACE ALL DAMAGED PARTS	New	800.00	200.00
2	CHECK WIRING AND LIGHTINGS	New	50.00	0.00
3	REMOVE AND REINSTALL REAR UPHOLSTERY, CUSHION SEATS AND ROOF LINING TO ENABLE REPAIR	New	150.00	0.00
4	REMOVE AND REPLACE REAR REVERSE SENSORS	New	100.00	40.00
5	RUST PROOFING TREATMENT ON AFFECTED AREA	New	120.00	0.00
6	SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	200.00
Gross Labour Cost (\$\$)			2,220.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >