

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



DATE : 05.09.2022

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJN193J**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 04.09.2022
TIME OF ACCIDENT : 09:00 HRS

MROS3ZEE106130966

Xiao Tony.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 490.00	\$ 490.00 ✓
2	FRONT BUMPER LOWER GRILLE <i>Distorted</i>	1	\$ 140.00	\$ 140.00 ✓
3	FRONT BUMPER LOGO <i>new</i>	1	\$ 85.00	\$ 85.00 ✓
4	FRONT BUMPER FOG LAMP <i>RH cracked</i>	2	\$ 300.00	\$ 600.00 300. ✓
5	FRONT BUMPER FOG LAMP WIRE HARNESS <i>new</i>	1	\$ 284.00	\$ 284.00 X.
6	FRONT BUMPER FOG LAMP COVER <i>new</i>	2	\$ 85.00	\$ 170.00 X.
7	FRONT BUMPER TOP RUBBER <i>cut</i>	1	\$ 75.00	\$ 75.00 ✓
8	FRONT BUMPER LOWER COVER GARNISH <i>torn</i>	2	\$ 100.00	\$ 200.00 ✓
9	FRONT BUMPER SIDE RETAINER <i>2nd</i>	2	\$ 75.00	\$ 150.00 ✓
10	FRONT BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 380.00	\$ 380.00 ✓
11	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 360.00	\$ 360.00 ✓
12	HEADLAMP <i>cracked</i>	2	\$ 780.00	\$ 1,560.00 ✓
13	HEAD LAMP LOWER BRACKET <i>new</i>	2	\$ 95.00	\$ 190.00 X.
14	FRONT FENDER INNER COWLING <i>torn</i>	2	\$ 170.00	\$ 340.00 ✓
15	BONNET STOPPER <i>new</i>	2	\$ 20.00	\$ 40.00 X.
16	BONNET LOCK <i>Distorted</i>	1	\$ 110.00	\$ 110.00 ✓
17	BONNET LOCK BRACE PANEL <i>Best</i>	1	\$ 118.00	\$ 118.00 ✓
18	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$ 750.00	\$ 750.00 ✓
19	HORN <i>new</i>	1	\$ 130.00	\$ 130.00 X.
20	AIR CONDENSOR <i>warpped</i>	1	\$ 1,510.00	\$ 1,510.00 1289

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJN193J**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 04.09.2022
 TIME OF ACCIDENT : 09:00 HRS

21	AIR CONDENSOR SUPPORT PANEL (TOP) <i>32415</i>	1	\$ 111.00	\$ 111.00	x
22	AIR CONDENSOR SUPPORT PANEL (BOTTOM)	1	\$ 111.00	\$ 111.00	x
23	RADIATOR <i>Dmgd.</i>	1	\$ 2,030.00	\$ 2,030.00	1450.
24	RADIATOR TOP BRACKET <i>new</i>	2	\$ 29.00	\$ 58.00	x
25	RADIATOR MOUNTING <i>new</i>	4	\$ 25.00	\$ 100.00	✓
26	WIPER WASHER TANK <i>new</i>	1	\$ 151.10	\$ 151.10	x
27	TEMPERATURE SENSOR <i>new</i>	1	\$ 191.10	\$ 191.10	x

7897
552275

TOTAL PRICE \$ 10,434.20
 LESS 25% \$ 2,608.55
SUB TOTAL PRICE \$ 7,825.65

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE (SPECIAL TYPE) <i>missing</i>	1	\$ 150.00	\$ 150.00	60.
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30.
3	FRONT BUMPER LOWER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
4	ENGINE UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	x
5	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	✓
6	FRONT SUPPORT PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	50.
7	RADIATOR COOLANT <i>new</i>	1	\$ 40.00	\$ 40.00	✓

260

TOTAL \$ 520.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600.
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
5	REFOCUS HEADLAMP BEAM	\$ 60.00	x

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJN193J**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 04.09.2022
TIME OF ACCIDENT : 09:00 HRS

6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	X
---	--	-----------	---

1520

TOTAL \$ 2,740.00

TOTAL PARTS COST : \$ 8,345.65
TOTAL LABOUR COST : \$ 2,740.00
TOTAL REPAIR COST : \$ 11,085.65

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

H/S 06 Days.

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 7702.75

4/s: 6150

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: