

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

05th SEP 2022

DDMS PRODUCTION
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

Accident date: 01ST SEP 2022

Estimated repair cost for vehicle no: SML1883U TOYOTA NOAH 1.8 ' 2019

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$1,774.20
2	1	Rear Boot Lid HYBIRD logo		\$40.00
3	1	Rear Boot Lid lock		\$385.10
4	1	Rear boot lid center moulding		\$315.00
5	6	Rear boot lid center moulding clips	\$6.50	\$39.00
6	1	Rear Boot Lid weatherstrip		\$285.00
7	1	Rear boot lid emble logo		\$75.00
8	1	Rear Boot Lid Number Plate		\$50.00
9	2	Rear Boot Lid Number Plate Lamp	\$58.50	\$117.00
10	1	Rear boot lid inner rubber		\$265.00
11	1	Rear Boot Lid Inner Trim board		\$552.10
12	1	Rear windscreen seal		\$215.30
13	2	boot lid side reflector	\$215.00	\$430.00
14	1	Rear Bumper		\$1,455.00
15	1	Rear bumper towing cover		\$68.00
16	2	Rear Bumper Side Reflector	\$85.00	\$170.00
17	2	Rear Bumper Side Bracket	\$155.00	\$310.00
18	2	rear bumper side retainer	\$135.00	\$270.00
19	2	Rear bumper mud shield	\$155.00	\$310.00
20	8	Rear bumper clips		\$50.00
21	1	Rear Bumper Reinforcement		\$658.00
22	1	Rear Bumper reverse sensor		\$350.00
23	1	Rear Boot Lid Inner Trim board handle		\$168.00
24	1	rear lower bumper		\$485.00
25	1	Antenna electrical key		\$425.00
26	1	end panel		\$783.20
27	1	end panel top garnish		\$258.20
28	1	Rear spare tire panel top sponge		\$265.30
29	1	Rear spare tire panel top cover		\$485.20
30	1	Rear spare tire panel sealant		\$250.00

Subtotal :-

\$11,303.60

Labour charges

To remove & re-fix cushion

\$120.00 60

to remove & Refix rear windscreen

\$120.00 /

Gum

\$50.00 40

to remove & Refix rear reverse sensor

\$120.00 X NN

To Check Wiring System

\$80.00 X NN

Tuff Kote

\$120.00 60

Panel beating

\$1,000.00 600

Spray painting

\$1,000.00 600

Subtotal :- \$2,610.00

Total:- \$13,913.60

5 Days.

4/5

Emo Qiang

82 880282

5/9/22

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal trade in parts allowed
- Supplementary parts are not surveyed and
is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: