



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22008805/Kcy3e2 Date: 18/07/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDF 5505Z	Veh. Inspected	SND 8472G	
Policy No.	P10708016R00	Coverage (\$)	0.00	
Claim No.	C10017181/KY	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	07/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250 (A)	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2120472A388953	Colour	METALLIC SILVER	
Odometer	208786 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/35 R19	MICHELIN	4 mm	
L/H Front Tyre	255/35 R19	MICHELIN	4 mm	
R/H Rear Tyre	275/30 R19	MICHELIN	5 mm	
L/H Rear Tyre	275/30 R19	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/08/2022	Inspection Date	08/09/2022	
Survey held at	LM AUTO SOLUTION PTE LTD BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-12, SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	