

ASS. REC. BY:

REF:

AG2/ 22 00 8805/KC

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP / 24 HRS

04/31

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SND 84726

Yr Regn:

05, 11

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E250

C.C.

1796

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

M. P. Silver

T/Radio:

Insured / Std / NI / NA

Eng/No:

208788

C/No:

WDD 2120472A 388953

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

255/35R19

R:

275/30R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

27/8/22

D.O.I.

8/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS, SI

F. 1.25

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Not Authorized
11 Sep 0
Permy Atk Piam
2 days

LM AUTO SOLUTION PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C,

#01-12 Singapore 575645

Email: admin@lmautosolution.com

Tel: 90162222

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

ENGINE NUM:

CHASSIS NUM:

SND 8472 G

MERC E250

ATTN:					
NO.	DESCRIPTION - PARTS		QTY	PRICE	
1	SIDE MIRROR ASSY	<i>Pr 1</i>	<i>1</i>	\$ 2,155.00	✓
2	FRONT DOOR RH		1	\$ <i>12</i> 2,844.00	X
3	FRONT DOOR W/STRIP RH		1	\$ <i>12</i> 263.00	X
4	FRONT DOOR OUTER MOULDING RH		1	\$ <i>12</i> 198.00	X
5	FRONT DOOR HANDLE RH		1	\$ <i>67</i> 296.00	✓
6	FRONT DOOR STICKER RH		1	\$ <i>12</i> 157.00	X
7	REAR DOOR RH		1	REPAIR	
SUBTOTAL				\$ 5,913.00	
10%				\$ 591.30	
PARTS TOTAL				\$ 5,321.70	
SPECIAL NETT			QTY	PRICE	
1	SIDE MIRROR CARBON FIBER GARNISH [SET]	<i>Pr 1</i>	<i>1</i>	\$ 1,200.00	✓
SPECIAL NETT				\$ 1,200.00	
LABOUR			QTY	PRICE	
1	TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA		1	\$ 600.00	<i>2001</i>
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		1	\$ 500.00	<i>3501</i>
3	TO RUST PROOF ACCIDENT AFFECTED AREA		1	\$ <i>12</i> 30.00	X
4	TO R & R FRONT DOOR MECHANISM RH		1	\$ <i>12</i> 180.00	X
5	TO R & R SIDE MIRROR AND RESET SYSTEM		1	\$ <i>12</i> 100.00	X
LABOUR TOTAL				\$ 1,410.00	
GRAND TOTAL COST				\$ 7,931.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: