



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS/ASM22008807/Avy3m4 Date: 15/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3099E	Veh. Inspected	SNC 9659J	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M04AHY	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	07/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC250	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDC2539462F415609	Colour	GREY	
Odometer	65198 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/35 R21	MICHELIN	6 mm	
L/H Front Tyre	295/35 R21	MICHELIN	6 mm	
R/H Rear Tyre	295/35 R21	MICHELIN	6 mm	
L/H Rear Tyre	295/35 R21	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2022	Inspection Date	12/09/2022	
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		