



友尼摩多公司 UNIMOTOR COMPANY

WDC2539462F415609

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 27/02/2023 OUR REF: UAPL1580
REPAIR ESTIMATE YOUR VEHICLE MERCEDES BENZ GLC250 NO SNC9659J

- 1 REAR R/H DOOR PANEL *new*
- 1 REAR R/H CENTRE STEP GARNISH *new*
- 1 REAR R/H FENDER PANEL *new*
- 1 REAR R/H FENDER OUTER GARNISH *new*
- 1 REAR R/H ABSORBER *new*
- 1 REAR R/H LOWER ARM *new*
- 1 REAR R/H KNUCKLE *new*
- 1 REAR R/H WHEEL HUB BEARING *new*
- 1 REAR BUMPER TOP *new*
- 1 REAR BUMPER LOWER *new*
- 1 REAR R/H SIDE RETAINER *new*

LESS 10%.....

SPECIAL NETT:

- 1 REAR R/H SPORT WHEEL *new*

LABOUR CHARGES

- TO SEND VEHICLE FOR COMPUTER ALIGNMENT
- TO SPARY UNDERCOATING IN REPAIR
- TO DISM/REWIRE REAR DAMAGED PORTION
- TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
- TO PUTTY AND RESPRAY DAMAGED PORTION

To dismantle undercarriage

\$	3,430.00	X
\$	1,652.00	X
\$	4,235.00	X
\$	312.00	X
\$	854.00	X
\$	371.00	X
\$	2,063.00	X
\$	917.00	X
\$	1,309.00	X
\$	674.00	X
\$	144.00	X
\$	15,961.00	
\$	1,596.10	
\$	14,364.90	

\$ 1,800.00 *1200*

\$ 120.00 *80*

\$ 150.00 X

\$ 250.00 X

\$ 1,000.00 *200*

\$ 1,000.00 X

\$ 18,684.90

1280

430

300
150

total: 3001.50

L/S: 2.4K

03 days

2.4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental survey must be resurveyed and is subject to confirmation from Insurance Company

Acknowledged by Repairer

Signature:

Date: