



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNA1712B

Model: MERCEDES GLA200 NEW MODEL

WIN247

No	Qty	Parts Description	Estimated Parts Price
1	1	Bumper assy	\$ 2,250.00 CRA1354 1454
2	2	Bumper side bracket	\$ 280.00 BT
3	2	Bumper side retainer	\$ 260.00 CUT/CRA192
4	2	△Bumper internal mounting center bracket	\$ 240.00 CRA200
5	2	Bumper lower reflector	\$ 200.00 NN
6	1	Bumper top silver trim /luggage	\$ 320.00 NEC250
7	1	Bumper lower trim-bumper diffuser	\$ 350.00 DD
8	1	Reinforcement	\$ 850.00 572DD
9	1	△Reinforcement top cover garnish bracket	\$ 380.00 de
10	2	Tailgate absorber	\$ 1,200.00 XNN
11	1	Emblem	\$ 165.35 NEC72
12	1	GLA200 logo	\$ 188.35 NEC105
13	1	Tailgate assy	\$ 2,600.00 BUC2371
14	1	△Tailgate /front trim cover	\$ 285.00 XNN
15	1	Tailgate lock	\$ 280.00 BT
16	1	Tailgate inner trim whole piece	\$ 295.00 CRA
17	1	Tailgate number plate light	\$ 120.00 XNN
18	1	Tailgate control button	\$ 200.00 XSVC
19	1	Tailgate rubber garnish	\$ 325.00 DD
20	1	Light bracket-left RH CRA	\$ 400.00 200
21	1	Tailight light	\$ 680.00 XNA
22	1	Tailight light (RH)	\$ 680.00 579
23	1	△Lower lip silving chrome	\$ 420.00 CRA
24	1	△Lower lip base	\$ 680.00 CRA540
25	2	△Exhaust base	\$ 300.00 CRA
26	2	Exhaust cover silver cover	\$ 380.00 XNN
27	1	Tow cover	\$ 170.00 XNN
28	2	Rear light support bracket	\$ 250.00 XNN
29	1	Switch sensor with cable	\$ 650.00 XNN
30	1	△Tailgate middle trim	\$ 380.00 XNN
31	1	Wheel arch trim-rear left	\$ 195.00 XNN
36	2	△Wheel arch trim -rear left	\$ 380.00 XNN
37	2	Rear lamp combination	\$ 180.00 XNN
38	1	Exhaust heat shield, need remove exhaust to replace	\$ 300.00 XSVC
39	1	△Sensor cable	\$ 250.00 XSVC
		Parts sub-total	\$ 17,083.00

9155
\$239.50
10/2 8149.50



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNA1712B

Modle: MERCEDES GLA200 NEW MODEL

No	Qty	Parts Description / Special Nett Item	Estimated Parts Price
1	10	Rear bumper clips	\$ 100.00 40 NEC
2	8	Rear end lower panel top garnish clips	\$ 80.00 30 NEC
3	1	Rear end lower panel sealant	\$ 120.00 XNN
4	8	Rear tailgate inner trim board clips	\$ 80.00 30 NEC
5	8	Rear tailgate outer garnish clips	\$ 80.00 30 NEC
6	12	Rear lower lip clips	\$ 100.00 XNN
	10	Bumper diffuser clips	\$ 100.00 XNN
7	1	Tailgate middle trim clips	\$ 120.00 XNN
8	1	Rear windscreen glass sealant -necessary to replace tailgate	\$ 120.00 50 NEC
9	8	Rear windscreen garnish clips -necessary to replace tailgate	\$ 80.00 XNN
10	1	Rear windscreen rubber seal -necessary for replace tailgate	\$ 150.00 40 NEC
11	6	Rear bumper reverse sensor - list item, subject to demand	\$ 1,500.00 short 430
12	1	Rear no plate with garnish	\$ 100.00 XNN
13	6	Sensor O-rings	\$ 120.00 90 3 NEC
14	6	Sensor bracket holder (inside bumper -one time only)	\$ 120.00 80 3 NEC
Special Nett Items			\$ 2,970.00

820



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNA1712B

Model: MERCEDES GLB200

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00 30
2	Carry up body cavity preservation for affected area \$80 per panel	\$ 320.00 40
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 2,500.00 600
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear end panel side cover x2, fender	\$ 2,000.00 500
5	To replacing rear undercarriage parts, including brake bleeding brake system etc.	\$ 120.00 X 111
6	Carry out wheel alignment	\$ 120.00 X 111
7	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 180.00 60
8	Transferring tailgate /bootlid lock mechanism, trimming etc to the new tailgate /bootlid	\$ 120.00 60
9	Removing and installing rear exhaust muffler assy to facilitate the repair	\$ 150.00 X
10	Checking central lock system for proper function	\$ 120.00 X
11	Checking auto door system for proper function	\$ 120.00 X
12	Removing and installing rear fender internal garnish and trimming to facilitate the necessary repair	\$ 150.00 X
13	Removing and installing rear window /windscreen glass	\$ 150.00 120
14	To remove and install rear camera	\$ 80.00 30
15	Transferring tailgate and rear end wiring harness for proper function	\$ 150.00 X Rpt
16	Water test after accident repair body work	\$ 120.00 X 111
17	Paint protection coating for accident affected areas	\$ 350.00 X 111
18	Carry out diagnosis check including cleaning accident fault code	\$ 150.00
19	Programming coding for accident repair work completed	\$ 600.00 } 180

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total labour : \$ 7,580.00

8239.50 1620

820

1620

10679.50

1588500, 6 days