



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

10 AM ON 08/09/2022

Date: 05/09/2022

Attn: The Motor Claims Department
Your Insured Vehicle - SJC 5013 X

Auto & General Insurance (Singapore) Pte Ltd
190 Clemenceau Ave #03-01 Singapore Shopping Centre
Singapore 239924
Tel: 62212199 Email: Claims@budgetdirect.com.sg

Yam (LKIC) 67418434

Veron.

WDD2130452A123188.

WITHOUT PREJUDICE

Dear Sir / Madam

Estimated Cost of repair for Vehicle Mercedes E250 SKD8768P & SJC5013X ON 30/08/2022 AT 17:17.

1pc	Rear Bumper	2599	\$ 2,050.00	Nett	✓
10pcs	Rear Bumper Clips		\$ 200.00	Nett	50
1pc	Rear Bumper Moulding	2339.10	\$ 350.00	Nett	✓
1pc	Rear Bumper Lower PAD		\$ 325.00	Nett	✓
2pcs	Reverse Sensor	2pcs X \$280	\$ 560.00	Nett	80
1pc	Rear Bumper Lamp		\$ 48.00	Nett	✓
			\$ 3,533.00		
Less 10%			-\$ 353.30		
			\$ 3,179.70		

To dismantl & replace damage parts, panel beat where necessary
To putty, apply primer & spray paint on the affected portion.
To remove reverse sensor.
To check wiring functions.

\$ 400.00 250
\$ 480.00 250
\$ 120.00 50
\$ 100.00 30
\$ 4,279.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
P/P 08/09/22
02 Days
Total: 2919.10
(P/P)