

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Vehicle Details

Make & Model : Honda SHUTTLE 1.5G CVT
SENSING
Chassis No : GK82101327
Registration No : SMZ7402L

Claim Details

Case Ref. No.: TR/092022/56219

Date: 08-09-2022

Accident Date: 05-09-2022

Third Party Vehicle Details

Registration No.: PC5624L

Acknowledged by Repairer

Signature:

Date:

S/N	Description	Qty	Amount (\$\$)
1	REAR RH DOOR / <i>blue</i>	1.00	\$799.50 ✓
2	REAR RH DOOR OUTER MOULDING X <i>NN</i>	1.00	\$53.80
3	REAR RH DOOR PILLAR STICKER / <i>blue</i>	1.00	\$25.10 ✓
4	REAR RH DOOR POWER WINDOW MOTOR WITH GEAR ? ✓ <i>BR</i>	1.00	\$248.70 ✓
5	REAR RH FENDER / <i>blue</i> (photo)	1.00	\$1,010.90 ✓
6	REAR RH FENDER GLASS X <i>NN</i>	1.00	\$680.30
7	RH SIDE SKIRT / <i>BR</i>	1.00	\$363.20 ✓
8	REAR RH WHEEL SPORT RIM / <i>cut</i>	1.00	\$450.40 ✓
9	REAR RH WHEEL SHOCK ABSORBER X <i>NN</i>	1.00	\$285.10
10	REAR RH WHEEL BEARING / <i>Im</i>	1.00	\$321.10 ✓
11	REAR AXLE X <i>NN</i> ✓ <i>BT</i>	1.00	\$950.20 ✓
			\$5,188.30
			(Discount: -20%)
			\$4,150.64
12	REAR RH WHEEL TYRE X <i>NN</i>	1.00	\$280.00
13	TO CHECK WHEEL ALIGNMENT	1.00	\$150.00 60 ✓
14	TO REMOVE AND REPLACE REAR RH FENDER GLASS	1.00	\$150.00 X <i>NN</i>
15	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	1.00	\$380.00 60 ✓
16	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$280.00 50 ✓
17	TO REPAIR DAMAGES	1.00	\$880.00 700 ✓
18	TO SPRAY PAINTING	1.00	\$980.00 880 ✓

4169.10

-20%

3335.28

Discount: -20%

1850

Subtotal w/o GST:

\$7,250.64

P/P - 5185.29

6 Days. 8/9/22
4/5 After repair photo's
Gmc Qicong

Issued by Raymond Teo

This is a computer-generated document. No signature is required.



Honda : Shuttle
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°29'	-0°29'	-1°00' 1°00'
4°39'	4°39'	4°00' 6°00'
-0°15'	-0°15'	-0°09' 0°09'
12°59'	12°59'	
12°30'	12°30'	

Front : Right

Actual	Before	Specified Range
0°03'	0°03'	-1°00' 1°00'
4°56'	4°56'	4°00' 6°00'
0°01'	0°01'	-0°09' 0°09'
12°40'	12°40'	
12°43'	12°43'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°32'	-0°32'	-1°00' 1°00'
-0°17'	-0°17'	
0°19'	0°19'	
-0°14'	-0°14'	-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-2°03'	-2°03'	-2°45' -0°45'
0°04'	0°04'	0°00' 0°17'

Rear : Right

Actual	Before	Specified Range
-3°51'	-3°51'	-2°45' -0°45'
-0°17'	-0°17'	0°00' 0°17'

Camber
Toe

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
1°48'	1°48'	-1°00' 1°00'
-0°13'	-0°13'	0°00' 0°34'
0°11'	0°11'	
0mm	0mm	