

Vehicle Damage Assessment Report for [SMA3200K]

Estimate Created: 07/09/2022 09:55 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/05/2023 13:29 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Subaru	Model	XV
Engine Type			
License Plate Number	SMA3200K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$1,150.00 WITH 3 WORKING DAYS

Insurlogic 4 (05/05/2023 13:27)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
FRONT FENDER LH		1	280.00	-20.00 %	224.00
FRONT FENDER PROTECTOR LH		1	140.90	-20.00 %	112.72
FRONT BUMPER		1	468.50	-20.00 %	374.80
FRONT BUMPER RRETAINER LH		1	15.70	-20.00 %	12.56
Parts Subtotal					724.08

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	300.00	0.00 %	300.00
Anti Rust coating	RnR	30.00	0.00 %	30.00
Check wiring	RnR	20.00	0.00 %	20.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 350.00

Paint Labor Subtotal 400.00

Labor Subtotal 750.00

Summary

Repair Cost 1,474.08

Discount(20 %) (294.82)

1,179.26

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 1,179.26