

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22008821/RPA3Q2**Date:** 20/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SMV6070M **Insured Vehicle No :** SKZ8727S  
 Date of Loss: 24/08/2022 Nature of Claim: TP Claim No: SP2002153638-01

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMV6070M**  
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G76707  
 Reg. Date: 12/10/2020 (Man. Year: 2020) Chassis No: JTDKB3FU603091269  
 Colour: Grey Odometer: 130617 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm  
 Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,725.75	737.25	3,988.50	84.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	900.00	1,250.00	58.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,875.75</b>	<b>1,637.25</b>	<b>5,238.50</b>	<b>76.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	6,875.75	1,300.00	5,575.75	81.09
<b>+ GST 8.00/8.00% (S\$)</b>	550.06	104.00	446.06	81.09
<b>Nett Amount (S\$)</b>	<b>7,425.81</b>	<b>1,404.00</b>	<b>6,021.81</b>	<b>81.09</b>
<b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		33.00		
<b>Nett Liability (S\$)</b>		<b>1,677.00</b>		

**INSPECTION**

Date of Assignment: 07/09/2022  
 Date Inspected: 07/09/2022 Inspected At: 60 JALAN LAM HUAT #05-18  
 Estimated Period of Repair: 3.0 days Repairer: My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ)

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2023)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMV6070M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	798.00 FL	*586.00 FL
2	1		*FRONT BUMPER SIDE COVER RH	Scratched	112.00 FL	*112.00 FL
3	1		*FRONT FENDER RH	Repair	698.00 FL	*- FL
4	1		*FRONT FENDER COWLING RH	Not Necessary	159.00 FL	*- FL
5	1		*FRONT FENDER EMBLEM RH	Necessary	45.00 FL	*45.00 FL
6	1		*SIDE SKIRTING RH	Not Necessary	898.00 FL	*- FL
7	1		*FRONT DOOR RH	Repair	1,025.00 FL	*- FL
8	1		*FRT LOWER ARM RH	Not Necessary	581.00 FL	*- FL
9	1		*FRT KNUCKLE ARM RH	Not Necessary	587.00 FL	*- FL
10	1		*FRT WHEEL BEARING RH	Not Necessary	198.00 FL	*- FL
11	1		*FRONT DOOR STICKER	Necessary	150.00 FS	*50.00 FS
12	1		*FRT FENDER INNERSHIELD CLIP SET RH	Not Necessary	50.00 FS	*- FS
13	1		*SIDE MIRROR CARBON FIBRE COVER	Scratched	200.00 FS	*80.00 FS
14	1		*FRONT RIM RH	Not Necessary	300.00 FS	*- FS
15	1		*SET FRONT WHEEL HUB CAP	Scratched	200.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,001.00</b>	<b>923.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,275.25	185.75
<b>Total Parts (S\$)</b>	<b>4,725.75</b>	<b>737.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING	New	100.00	0.00
2	R+R UNDERCARRIAGE	New	350.00	0.00
3	WHEEL ALIGNMENT	New	100.00	0.00
4	KNOCK	New	800.00	300.00
5	SPRAY	New	800.00	600.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,150.00</b>
				<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >