



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

## Estimation

Date: 7/9/2022  
 Vehicle: SMV6070M  
 Make / Model: TOYOTA PIRUS  
 Chassis No: ALLIANZ

No.	Description	Unit	Unit Price	Amount
<b>Parts Replacement:</b>				
1	FRONT BUMPER <i>scr</i>	1	\$ 798.00	\$ 798.00
2	FRONT BUMPER SIDE COVER RH <i>scr</i>	1	\$ 112.00	\$ 112.00
3	FRONT FENDER RH <i>repair</i> X	1	\$ 698.00	\$ 698.00
4	FRONT FENDER COWLING RH X nn	1	\$ 159.00	\$ 159.00
5	FRONT FENDER EMBLEM RH <i>scr</i>	1	\$ 45.00	\$ 45.00
6	SIDE SKIRTING RH X nn	1	\$ 898.00	\$ 898.00
7	FRONT DOOR RH <i>repair</i>	1	\$ 1,025.00	\$ 1,025.00
8	FRT LOWER ARM RH X nn	1	\$ 581.00	\$ 581.00
9	FRT KNUCKLE ARM RH X nn	1	\$ 587.00	\$ 587.00
10	FRT WHEEL BEARING RH X nn	1	\$ 198.00	\$ 198.00
TOTAL PART				\$ 5,101.00
LIST DOWN		25%		\$ 1,275.25
AFTER LIST DOWN				\$ 3,825.75
<b>SPECIAL NETT</b>				
1	FRONT DOOR STICKER <i>scr</i>	1	\$ 150.00	\$ <del>150.00</del>
2	FRT FENDER INNERSHIELD CLIP SET RH X nn	1	\$ 50.00	\$ 50.00
3	SIDE MIRROR CARBON FIBRE COVER <i>scr</i>	1	\$ 200.00	\$ <del>200.00</del>
4	FRONT RIM RH X nn	1	\$ 300.00	\$ 300.00
5	FRONT WHEEL HUB CAP SET <i>scr</i>	1	\$ 200.00	\$ <del>200.00</del>
TOTAL AMOUNT				\$ 900.00
<b>LABOUR</b>				
1	CHECK WIRING			\$ <del>100.00</del>
2	R+R UNDERCARRIAGE			\$ 350.00
3	WHEEL ALIGNMENT			\$ 100.00
4	KNOCK			\$ <del>800.00</del>
5	SPRAY			\$ <del>800.00</del>
TOTAL AMOUNT				\$ 2,150.00
			Parts Replacement Amount	\$ 5,976.00
			Total Amount for Labour	\$ 2,390.00
			<b>Total Amount</b>	\$ 8,366.00

586 ✓  
 ✓  
 ✓  
 ✓  
 743  
 -25%  
 557.25

50  
 80  
 50  
 180

X  
 X  
 X  
 300  
 600

900

1637.25  
 L/S - 1309.80  
 = 1300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Repair*  
*HP 900000*  
*3 days*  
*4/8*  
*07/09/22 @ 1700*  
*Resy after repair*