

Ashu

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

VEHICLE No: GBG 2510X

not Allowed
 per
 8/9/22
 2/s \$5600
 5 days

				NETT ITEM
1PC	FRONT BUMPER	gread	632.20	\$945.20 ✓
1PC	FRONT BUMPER SIDE RETAINER N/S	Burf	35.00	\$66.50 ✓
1PC	FRONT BUMPER BEAM	11		\$315.00 X
1PC	FRONT BUMPER SPONGE	to.n	145.00	\$188.00 ✓
1PC	HEADLAMP N/S	BRO	865.20	\$1,650.00 ✓
1PC	HEADLAMP LOWER GARNISH N/S	to.n	348.00	\$605.00 ✓
1PC	FRONT GRILLE	one	381.30	\$588.10 ✓
1PC	FRONT FENDER N/S	11		\$645.10 X
1PC	FRONT FENDER INNER SHIELD N/S	11		\$182.50 X
1PC	BONNET	DO/SUC	1066.20	\$1,266.00 ✓
2PCS	BONNET HINGES @\$165.00	two 1/5 x 2 = 230		\$330.00 ✓
1PC	BONNET LOCK	11		\$166.00 X
1PC	BONNET INSULATOR	11		\$282.00 X
1PC	FRONT SUPPORT PANEL	DO/SUC	645.00	\$845.20 ✓
1PC	AIR CON CONDENSER	gun	820	\$1,522.00 ✓
1PC	AIR CON CONDENSER SIDE GARNISH N/S	de/to.n	128	\$186.00 ✓
1PC	RADIATOR	Burf gun	805	\$1,755.20 ✓
			(102	\$11,537.80

1SET	FRONT BUMPER CLIPS	111	\$30.00 ✓
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	11	\$30.00 X
1SET	BONNET INSULATOR CLIPS	111	\$50.00 ✓
1PC	FRONT LICENCE PLATE	11	\$50.00 X

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$100.00	60
TO REFILL AIR CON GAS	\$120.00	100
TO DIAGNOSTIC & REPROGRAMME SYSTEM	11	\$180.00 X
TO CONDUCT WHEEL ALIGNMENT	11	\$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$900.00	800
TO PUTTY & SPRAY PAINTING	\$1,080.00	800
TOTAL	\$14,227.80	

5800.90
 103
 5220.81
 80
 1780
 7080.81