

(08/11/13)

wef

REF:

CS/SMR22008698/Ray³

369k

ASS. REC. BY:

Ranu

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 63372

at Workshop m/s STRIKES (SMR)

of 60,000,000 (ML PK 04)

Insured: SMR

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD 63372

Yr Regn: 2016 FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIMS TAXI

c.c 1798

Colour:

MAROON

A/C: Insured / Std / NI / NA

Sp. Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN36U905767337

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Order~~ / Jammed / Leaked / Burnt orBrake: ~~Order~~ / Jammed / Leaked / Burnt orModi: ~~Nil~~ / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

SAILUN

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

01/01/22

D.O.I.

05/09/22

Survey held at

STRIKES

Des. of Damages: ~~Front~~ / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 6k

Rasul finalised LS \$6000, 8 days. (Red \$57525.74, 91%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Report Format :

TP

Lump Sum ~~4.1k~~ (\$) 6000

Add Fee:



: Site Insp (\$)

) S + RS, SI



: Interview (\$)

) Photos



: Tech. Invs (\$)

) Others



: Weekend (\$)

)

TOTAL



Case Details

Case Reference Number : TAX/09/22/2005

Type of Repair : Accident Repair

Vehicle Registration Number : SHD6337Z

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-19265-ID

Assigned By : Wei Siong #

Insurance Company Name : income insurance limited

Accident Date and Time : 01/09/2022 01:40 PM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	602.60	602.60	25.00	451.95	Replace	1	451.9	Replace ▾	der
One Time Key In	Main			BUMPER CLIPS (10 PCS)	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace ▾	der
One Time Key In	Main			BUMPER SUPPORT F/RH	1	86.20	86.20	25.00	64.65	Replace	0	0	Check ▾	?
One Time Key In	Main			BUMPER SUPPORT F/LH	1	86.20	86.20	25.00	64.65	Replace	0	0	Check ▾	?
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	97.60	97.60	25.00	73.20	Replace	0	0	Check ▾	?
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	567.90	567.90	25.00	425.92	Replace	0	0	Check ▾	?
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	284.00	284.00	25.00	213.00	Replace	0	0	Not Give ▾	Xan

One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	284.00	284.00	25.00	213.00	Replace	0	0	Not Give	?	Xan
One Time Key In	Main			DEFLECTOR, RADIATOR RH	1	94.30	94.30	25.00	70.72	Replace	0	0	Not Give	?	Xan
One Time Key In	Main			DEFLECTOR, RADIATOR LH	1	86.90	86.90	25.00	65.18	Replace	0	0	Not Give	?	Xan
Total Spare Part Cost											0	0	Surveyor Total		7,843.70
Lump Sum Discount (%)										20.00	Lump Sum Dis (%)		0		?
Bracket, FR BUMPER										126.10	Bracket, FR BUMPER		0		?
Final Spare Part Cost										35,301.59	Final Sur Total		7,843.70		

9/5/22, 4:52 PM

One Time Key In	Main	Portion	Material Number	NUMBER PLATE	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Replace	1	Surveyor Final Price(\$)	Surveyor Approval Replace	Remarks
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	64-
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	21.40	21.40	25.00	16.05	Replace	0	0	Not Give	X11
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	21.40	21.40	25.00	16.05	Replace	0	0	Not Give	X11
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	389.90	389.90	25.00	292.42	Replace	1	292.4	Replace	cr
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	318.50	318.50	10.00	286.65	Replace	0	0	Not Give	X11
One Time Key In	Main			THERMISTOR ASSY	1	142.30	142.30	10.00	128.07	Replace	0	0	Not Give	X11
One Time Key In	Main			FOG LAMP RH	1	335.60	335.60	10.00	302.04	Replace	0	0	Not Give	X11
One Time Key In	Main			FOG LAMP LH	1	319.30	319.30	10.00	287.37	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	32.30	32.30	25.00	24.22	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN CENTER RH	1	76.60	76.60	25.00	57.45	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	34.40	34.40	25.00	25.80	Replace	0	0	Not Give	X11
One Time Key In	Main			LENS & BODY, FR TURN LH	1	581.40	581.40	10.00	523.26	Replace	0	0	Not Give	X11
One Time Key In	Main			LENS & BODY, FR TURN RH	1	581.40	581.40	10.00	523.26	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	32.40	32.40	25.00	24.30	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	76.60	76.60	25.00	57.45	Replace	0	0	Not Give	X11

One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	34.50	34.50	25.00	25.88	Replace	0	0	Not Give	X11
One Time Key In	Main			EMBLEM FRONT	1	98.70	98.70	25.00	74.03	Replace	1	74.03	Replace	new
One Time Key In	Main			HOOD END PANEL SEAL	1	80.60	80.60	25.00	60.45	Replace	1	60.45	Replace	new
One Time Key In	Main			COVER, RADIATOR	1	139.30	139.30	25.00	104.48	Replace	1	104.4	Replace	cr
					Total Spare Part Cost					44,126.99				
					Lump Sum Discount (%)					20.00				
					Final Spare Part Cost					35,301.59				
					Surveyor Total					7,843.70				
					Lump Sum Dis (%)					0				
					Final Sur Total					7,843.70				

One Time Key In	Main	Portion	Material Number	GRILLE, RADIATOR	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval Replace	Remarks
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	118.30	118.30	25.00	88.72	Replace	0	0	Not Give	Xm
One Time Key In	Main			BUMPER LIP FRT	1	182.70	182.70	25.00	137.02	Replace	0	0	Not Give	Xm
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	159.30	159.30	25.00	119.48	Replace	0	0	Not Give	Xm
One Time Key In	Main			UNDER COVER CENTER	1	511.20	511.20	25.00	383.40	Replace	0	0	Not Give	Xm
One Time Key In	Main			UNDER COVER SIDE/LH	1	52.50	52.50	25.00	39.38	Replace	0	0	Not Give	Xm
One Time Key In	Main			UNDER COVER SIDE/RH	1	52.50	52.50	25.00	39.38	Replace	0	0	Not Give	Xm
One Time Key In	Main			HOOD PANEL	1	988.50	988.50	25.00	741.38	Replace	1	741.3	Replace	bt
One Time Key In	Main			HOOD PANEL INSULATOR	1	445.00	445.00	25.00	333.75	Replace	0	0	Not Give	Xm
One Time Key In	Main			HOOD HINRE LH	1	63.70	63.70	25.00	47.78	Replace	1	47.78	Replace	bt
One Time Key In	Main			HOOD HINGE RH	1	63.70	63.70	25.00	47.78	Replace	1	47.78	Replace	bt
One Time Key In	Main			WIPER GARNISH	1	699.00	699.00	25.00	524.25	Replace	0	0	Check	?
One Time Key In	Main			WIPER GARNISH COVER,LH	1	27.30	27.30	25.00	20.48	Replace	0	0	Check	?
One Time Key In	Main			WIPER GARNISH COVER,RH	1	27.30	27.30	25.00	20.48	Replace	0	0	Check	?
One Time Key In	Main			HOOD LOCK	1	146.10	146.10	25.00	109.57	Replace	1	109.5	Replace	bt
One Time Key In	Main			CABLE ASSY,HOOD	1	59.70	59.70	25.00	44.78	Replace	0	0	Not Give	Xm

One Time Key In	Main			HOOD AUXILIARY CATCH	1	10.00	10.00	25.00	7.50	Replace	0	0	Check	?
One Time Key In	Main			CLAMP, HOOD LOCK	1	6.70	6.70	25.00	5.03	Replace	0	0	Check	?
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace	der
One Time Key In	Main			BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	10	18.00	Replace	der
					Total Spare Part Cost		44,126.99		Lump Sum Discount (%)		20.00		Surveyor Total	
									24.00		18.00		7,843.70	
					Final Spare Part Cost		35,301.59				Final Sur Total		7,843.70	

One Time Key In	Main	Portion	Material Number	SMRT Recommendation	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval Check	Remarks
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	234.70	234.70	25.00	176.02	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check	?
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	208.10	208.10	10.00	187.29	Replace	0	0	Check	?
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	?
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Check	?
One Time Key In	Main			BUMPER SEAL, RR RH	1	74.40	74.40	25.00	55.80	Replace	0	0	Check	?
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	93.90	93.90	25.00	70.43	Replace	1	70.43	Replace	scr
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	155.40	155.40	25.00	116.55	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			BUMPER LIP REAR	1	301.90	301.90	25.00	226.42	Replace	1	226.4	Replace	scr
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	586.10	586.10	25.00	439.58	Replace	0	0	Check	?
One Time Key In	Main			UNDER COVER RR SHIELD	1	66.10	66.10	25.00	49.57	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			HORN ASSY, HIGH	1	145.90	145.90	10.00	131.31	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			HORN ASSY, LOW	1	145.90	145.90	10.00	131.31	Replace	0	0	Not Give	X ₁₁

One Time Key In	Main			HEAD LAMP LH	1	1,075.40	1,075.40	10.00	967.86	Replace	0	0	Check	?
One Time Key In	Main			HEAD LAMP RH	1	1,075.40	1,075.40	10.00	967.86	Replace	1	967.8	Replace	scr
One Time Key In	Main			TUBE & ACCESSORY	1	830.50	830.50	25.00	622.88	Replace	0	0	Not Give	X ₁₁
						Total Spare Part Cost			44,126.99			Surveyor Total	7,843.70	
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,839.70	1,839.70	25.00	1,379.78	Replace	1	1,379	Replace	bt
						Lump Sum Discount (%)			20.00			Lump Sum Dis (%)	0	
						Final Spare Part Cost			35,301.59			Final Sur Total	7,843.70	

One Time Key In	Main	Portion	Material Number	HOSE SUB-ASSY DISCHARGE Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Replace Repair/ Replace	0 Surveyor Quantity	0 Surveyor Final Price(\$)	Surveyor Approval Check Repair/Replace	?
One Time Key In	Main			A/C CONDENSER	1	1,695.90 Unit(\$)	1,695.90	25.00	1,271.93	Replace	0	0	Check	?
One Time Key In	Main			HOSE SUB-ASSY SUCTION	1	534.40	534.40	25.00	400.80	Replace	0	0	Check	?
One Time Key In	Main			RADIATOR ASSY UPPER	1	888.20	888.20	25.00	666.15	Replace	0	0	Check	?
One Time Key In	Main			HOSE, INVERTER NO.1	1	104.70	104.70	25.00	78.53	Replace	0	0	Check	?
One Time Key In	Main			HOSE, INVERTER COOLING NO.5	1	164.70	164.70	25.00	123.52	Replace	0	0	Check	?
One Time Key In	Main			RADIATOR ASSY	1	2,245.70	2,245.70	25.00	1,684.27	Replace	0	0	Check	?
One Time Key In	Main			CUSHION, RADIATOR (2 PCS)	2	14.80	29.60	25.00	22.20	Replace	0	0	Check	?
One Time Key In	Main			SUPPORT RADIATOR, LH	1	23.40	23.40	25.00	17.55	Replace	0	0	Check	?
One Time Key In	Main			SUPPORT RADIATOR, RH	1	72.00	72.00	25.00	54.00	Replace	0	0	Check	?
One Time Key In	Main			SUPPORT, RADIATOR (2 PCS)	2	24.80	49.60	25.00	37.20	Replace	2	37.20	Replace	✓
One Time Key In	Main			RADIATOR LOWER SUPPORT	1	1,004.70	1,004.70	25.00	753.53	Replace	0	0	Not Give	Xm
One Time Key In	Main			RADIATOR HOSE LOWER	1	56.00	56.00	25.00	42.00	Replace	0	0	Not Give	Xm
One Time Key In	Main			RADIATOR TOP HOSE NO 1	1	56.00	56.00	25.00	42.00	Replace	0	0	Check	?
One Time Key In	Main			RADIATOR HOSE BYPASS NO.1	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	Xm
One Time Key In	Main			RADIATOR HOSE BYPASS NO.2	1	38.30	38.30	25.00	28.72	Replace	0	0	Not Give	Xm

One Time Key In	Main			RADIATOR HOSE BYPASS NO.3	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	Xm
One Time Key In	Main			RADIATOR HOSE BYPASS NO.4	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	Xm
One Time Key In	Main			INVERTER BRACKET TRAY	1	330.80	330.80	25.00	248.10	Replace	0	0	Not Give	Xm
Total Spare Part Cost											0	0	Surveyor Total	7,843.70
One Time Key In	Main			INVERTER RADIATOR CUSHION	1	7.20	7.20	25.00	5.40	Replace	0	0	Not Give	Xm
Lump Sum Discount (%)											0	0	Lump Sum Dis (%)	0
Final Spare Part Cost											0	0	Final Sur Total	7,843.70

One Time Key In	Main	Portion	Material Number	INVERTER W CONVERTER Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COOLANT (ADD QTY)	1	12.32 Unit(\$)	12.32	0.00	12.32	Replace	1	12.32	Replace	✓
One Time Key In	Main			COOLANT RESERVE TANK	1	521.40	521.40	25.00	391.05	Replace	0	0	Check	?
One Time Key In	Main			FAN SHROUD	1	321.40	321.40	25.00	241.05	Replace	0	0	Check	?
One Time Key In	Main			FAN SHROUD TOP	1	131.50	131.50	25.00	98.63	Replace	0	0	Check	?
One Time Key In	Main			FAN BLADE	1	236.90	236.90	25.00	177.68	Replace	0	0	Check	?
One Time Key In	Main			FAN BLADE NO.2	1	305.50	305.50	25.00	229.13	Replace	0	0	Check	?
One Time Key In	Main			FAN MOTOR NO.1	1	708.40	708.40	10.00	637.56	Replace	0	0	Check	?
One Time Key In	Main			FAN MOTOR NO.2	1	708.40	708.40	10.00	637.56	Replace	0	0	Check	?
One Time Key In	Main			COVER CYLINDER	1	218.10	218.10	25.00	163.57	Replace	0	0	Not Give	Xn
One Time Key In	Main			INLET ASSY, AIR	1	262.20	262.20	25.00	196.65	Replace	0	0	Not Give	Xn
One Time Key In	Main			AIR CLEANER ASSY	1	1,234.80	1,234.80	25.00	926.10	Replace	1	926.1	Replace	Xca ✓
One Time Key In	Main			WIRE, ENGINE ROOM	1	6,693.70	6,693.70	10.00	6,024.33	Replace	0	0	Not Give	Xn
One Time Key In	Main			WIRE, ENGINE ROOM, NO.2	1	256.40	256.40	10.00	230.76	Replace	0	0	Not Give	Xn
One Time Key In	Main			ENGINE MOULDING BRACKET, FRONT	1	99.90	99.90	25.00	74.93	Replace	0	0	Not Give	Xn
One Time Key In	Main			ENGINE MOULDING FRT	1	260.00	260.00	25.00	195.00	Replace	0	0	Not Give	Xn

One Time Key In	Main			END PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Not Give	Xn
One Time Key In	Main			SPARE TYRE PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Not Give	Xn
One Time Key In	Main			TAILGATE ASY	1	1,260.70	1,260.70	25.00	945.53	Replace	1	945.5	Replace	bt ✓
Total Spare Part Cost												7,843.70		
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	33.60	33.60	25.00	25.20	Replace	1	25.20	Replace	✓
Lump Sum Discount (%)												0		
Final Spare Part Cost												7,843.70		
Final Sur Total														

One Time Key In	Material Number	Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Approval Replace	Remarks
One Time Key In	Main	TAILGATE DOOR GLASS MOULDING, LH	1	33.60	33.60	25.00	25.20	Replace	1	25.20	Replace	me ✓
One Time Key In	Main	TAILGATE DOOR GLASS	1	1,273.10	1,273.10	25.00	954.82	Replace	0	0	Not Give	Xnn
One Time Key In	Main	MOULDING BACK WINDOW, LOWER NO.1	1	33.60	33.60	25.00	25.20	Replace	1	25.20	Replace	me ✓
One Time Key In	Main	MOULDING, BACK WINDOW, LOWER NO.2	1	33.60	33.60	25.00	25.20	Replace	1	25.20	Replace	me ✓
One Time Key In	Main	TAILGATE LOWER WINDOW GLASS	1	827.50	827.50	25.00	620.63	Replace	0	0	Not Give	Xnn
One Time Key In	Main	DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	31.30	31.30	25.00	23.48	Replace	1	23.48	Replace	me ✓
One Time Key In	Main	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	22.30	22.30	25.00	16.73	Replace	1	16.73	Replace	me ✓
One Time Key In	Main	TROUGH, BACK DOOR	1	126.80	126.80	25.00	95.10	Replace	0	0	Not Give	Xnn
One Time Key In	Main	SEALANT W/SCREEN (3PCS)	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	me ✓
One Time Key In	Main	TAILGATE DOOR HINGE LH/RH (2 PCS)	2	61.20	122.40	25.00	91.80	Replace	0	0	Not Give	Xnn
One Time Key In	Main	TAILGATE DOOR STAY LH	1	253.40	253.40	25.00	190.05	Replace	0	0	Not Give	Xnn
One Time Key In	Main	TAILGATE DOOR STAY RH	1	253.40	253.40	25.00	190.05	Replace	0	0	Not Give	Xnn
One Time Key In	Main	TAILGATE DOOR LOCK	1	631.90	631.90	10.00	568.71	Replace	0	0	Not Give	Xnn
One Time Key In	Main	TAILGATE LOCK, COVER	1	20.70	20.70	25.00	15.52	Replace	0	0	Not Give	Xnn
One Time Key In	Main	STRIKER, BACK DOOR	1	55.80	55.80	25.00	41.85	Replace	0	0	Not Give	Xnn
One Time Key In	Main	TAILGATE DOOR WEATHER STRIP	1	402.50	402.50	25.00	301.88	Replace	1	301.8	Replace	me ✓
One Time Key In	Main	EMBLEM REAR	1	68.70	68.70	25.00	51.53	Replace	0	0	Not Give	Xnn
One Time Key In	Main	TAILGATE OUTSIDE GARNISH	1	574.80	574.80	25.00	431.10	Replace	0	0	Not Give	Xnn
One Time Key In	Main	NAME PLATE (HYBRID)	1	59.20	59.20	25.00	44.40	Replace	1	44.40	Replace	me ✓
One Time Key In	Main	NAME PLATE (PRUIS)	1	69.40	69.40	25.00	52.05	Replace	0	0	Not Give	me ✓
				Total Spare Part Cost				44,126.99				
				Lump Sum Discount (%)				20.00				
				Final Sur Total				7,843.70				

One Time Key In	Main	Portion	Material Number	Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval Not Give	Remarks
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	Xnn
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	Xnn
One Time Key In	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xnn
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP LH	1	618.60	618.60	10.00	556.74	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	35.20	35.20	25.00	26.40	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP RH	1	618.60	618.60	10.00	556.74	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	35.20	35.20	25.00	26.40	Replace	0	0	Not Give	Xnn
Standard	Main			WINDSCREEN FRT	1	1,543.80	1,543.80	25.00	1,157.85	Replace	0	0	Not Give	replace can ✓
Standard	Main			WINDSCREEN MOULDING FRT	1	57.60	57.60	25.00	43.20	Replace	1	0.00	Replace	✓
Standard	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	0.00	Replace	✓
Total Spare Part Cost										44,126.99	Surveyor Total		7,843.70	
Lump Sum Discount (%)										20.00	Lump Sum Dis (%)		0	
Final Spare Part Cost										35,301.59	Final Sur Total		7,843.70	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,014.00	600	
2	Main	TO REPAIR REAR PORTION	1,014.00	400	
Total:			2,028.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT HOOD	378.00	200	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	378.00	200	

Total:

2,430.00

1,000.00

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO RESPRAY TAIL GATE	378.00	200	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0 <i>Xan</i>	
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0 <i>Xan</i>	
7	Main	TO RESPRAY REAR PANEL	180.00	0 <i>Xan</i>	
8	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			2,430.00	1,000.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0 ?	receipt
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60	
4	Main	TO TOP UP A/C GAS	120.00	80	
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
7	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
8	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Xan</i>	
10	Main	TO CONDUCT RADIATOR PRESSURE CHECK	120.00	0 <i>Xan</i>	
11	Main	TO REMOVE / REFIT WINDSCREEN	120.00	120.00	
12	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	450.00	450.00	
Total:			1,962.88	1,266.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	35,301.59	7,843.70
Total Labour Cost	2,028.00	1,000.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spray Painting	2,430.00	1,000.00
Other	1,962.88	1,266.88
Overall Total	41,722.47	11,110.58
Lump Sum Repair Option	☐	☒
Lump Sum Total	41,700.00	11,100.00
Surveyor Approved Amount		11,100.00
No of Repair Days*	10	8
Remarks		lump sum repair / resurvey after repair request for NBV
Surveyor Name		Rasul
Signature		
Survey Date	05/09/2022	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHD6337Z
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6576689
Chassis No.:	JTDKN36U905767337
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	05 Feb 2016
First Registration Date:	05 Feb 2016
Transfer Count: -	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2024
PARF Rebate Amount:	\$3,250.00
COE Expiry Date:	04 Feb 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$43,040.00
COE Rebate Amount:	\$7,596.00
Total Rebate Amount:	\$10,846.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Sep 2022

OK