



Case Details

Case Reference Number : TAX/09/22/2005

Type of Repair : Accident Repair

Vehicle Registration Number : SHD6337Z

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-19265-ID

Assigned By : Wei Siong #

Insurance Company Name : income insurance limited

Accident Date and Time : 01/09/2022 01:40 PM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	602.60	602.60	25.00	451.95	Replace	1	451.9	Replace v	
One Time Key In	Main			BUMPER CLIPS (10 PCS)	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace v	
One Time Key In	Main			BUMPER SUPPORT F/RH	1	86.20	86.20	25.00	64.65	Replace	0	0	Check v	
One Time Key In	Main			BUMPER SUPPORT F/LH	1	86.20	86.20	25.00	64.65	Replace	0	0	Check v	
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	97.60	97.60	25.00	73.20	Replace	0	0	Check v	
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	567.90	567.90	25.00	425.92	Replace	0	0	Check v	
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	284.00	284.00	25.00	213.00	Replace	0	0	Not Give v	

One Time Key In	Main	ARM SUB-ASSY,FR BUMPER RH	1	284.00	284.00	25.00	213.00	Replace	0	0	Not Give	Xan		
One Time Key In	Main	DEFLECTOR, RADIATOR RH	1	94.30	94.30	25.00	70.72	Replace	0	0	Not Give	Xan		
One Time Key In	Main	DEFLECTOR, RADIATOR LH	1	86.90	86.90	25.00	65.18	Replace	0	0	Not Give	Xan		
				Total Spare Part Cost					0	0	Surveyor Total	7,843.70	Xan	
				Lump Sum Discount (%)				20.00						
One Time Key In	Main	BRACKET, FR BUMPER	1	126.10	126.10	25.00	94.57	Replace	0	0	Check	?		
				Final Spare Part Cost				35,301.59						
									Final Sur Total					7,843.70

9/5/22, 4:52 PM

One Time Key In	Main	Portion	Material Number	NUMBER PLATE	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Replace	1	Surveyor Final Price(\$)	Surveyor Approval Replace	Remarks
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	64-
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	21.40	21.40	25.00	16.05	Replace	0	0	Not Give	X11
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	21.40	21.40	25.00	16.05	Replace	0	0	Not Give	X11
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	389.90	389.90	25.00	292.42	Replace	1	292.4	Replace	CR
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	318.50	318.50	10.00	286.65	Replace	0	0	Not Give	X11
One Time Key In	Main			THERMISTOR ASSY	1	142.30	142.30	10.00	128.07	Replace	0	0	Not Give	X11
One Time Key In	Main			FOG LAMP RH	1	335.60	335.60	10.00	302.04	Replace	0	0	Not Give	X11
One Time Key In	Main			FOG LAMP LH	1	319.30	319.30	10.00	287.37	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	32.30	32.30	25.00	24.22	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN CENTER RH	1	76.60	76.60	25.00	57.45	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	34.40	34.40	25.00	25.80	Replace	0	0	Not Give	X11
One Time Key In	Main			LENS & BODY, FR TURN LH	1	581.40	581.40	10.00	523.26	Replace	0	0	Not Give	X11
One Time Key In	Main			LENS & BODY, FR TURN RH	1	581.40	581.40	10.00	523.26	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	32.40	32.40	25.00	24.30	Replace	0	0	Not Give	X11
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	76.60	76.60	25.00	57.45	Replace	0	0	Not Give	X11

One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	34.50	34.50	25.00	25.88	Replace	0	0	Not Give	X11
One Time Key In	Main			EMBLEM FRONT	1	98.70	98.70	25.00	74.03	Replace	1	74.03	Replace	new
One Time Key In	Main			HOOD END PANEL SEAL	1	80.60	80.60	25.00	60.45	Replace	1	60.45	Replace	new
One Time Key In	Main			COVER, RADIATOR	1	139.30	139.30	25.00	104.48	Replace	1	104.4	Replace	CR
					Total Spare Part Cost					44,126.99				
					Lump Sum Discount (%)					20.00				
					Final Spare Part Cost					35,301.59				
					Surveyor Total					7,843.70				
					Lump Sum Dis (%)					0				
					Final Sur Total					7,843.70				

One Time Key In	Main	Portion	Material Number	Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval Replace	Remarks
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	118.30	118.30	25.00	88.72	Replace	0	0	Not Give	Xm
One Time Key In	Main			BUMPER LIP FRT	1	182.70	182.70	25.00	137.02	Replace	0	0	Not Give	Xm
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	159.30	159.30	25.00	119.48	Replace	0	0	Not Give	Xm
One Time Key In	Main			UNDER COVER CENTER	1	511.20	511.20	25.00	383.40	Replace	0	0	Not Give	Xm
One Time Key In	Main			UNDER COVER SIDE/LH	1	52.50	52.50	25.00	39.38	Replace	0	0	Not Give	Xm
One Time Key In	Main			UNDER COVER SIDE/RH	1	52.50	52.50	25.00	39.38	Replace	0	0	Not Give	Xm
One Time Key In	Main			HOOD PANEL	1	988.50	988.50	25.00	741.38	Replace	1	741.3	Replace	bt
One Time Key In	Main			HOOD PANEL INSULATOR	1	445.00	445.00	25.00	333.75	Replace	0	0	Not Give	Xm
One Time Key In	Main			HOOD HINRE LH	1	63.70	63.70	25.00	47.78	Replace	1	47.78	Replace	bt
One Time Key In	Main			HOOD HINGE RH	1	63.70	63.70	25.00	47.78	Replace	1	47.78	Replace	bt
One Time Key In	Main			WIPER GARNISH	1	699.00	699.00	25.00	524.25	Replace	0	0	Check	?
One Time Key In	Main			WIPER GARNISH COVER,LH	1	27.30	27.30	25.00	20.48	Replace	0	0	Check	?
One Time Key In	Main			WIPER GARNISH COVER,RH	1	27.30	27.30	25.00	20.48	Replace	0	0	Check	?
One Time Key In	Main			HOOD LOCK	1	146.10	146.10	25.00	109.57	Replace	1	109.5	Replace	bt
One Time Key In	Main			CABLE ASSY,HOOD	1	59.70	59.70	25.00	44.78	Replace	0	0	Not Give	Xm

One Time Key In	Main	HOOD AUXILIARY CATCH	1	10.00	10.00	25.00	7.50	Replace	0	0	Check	?
One Time Key In	Main	CLAMP, HOOD LOCK	1	6.70	6.70	25.00	5.03	Replace	0	0	Check	?
One Time Key In	Main	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace	der
				Total Spare Part Cost						Surveyor Total	7,843.70	
One Time Key In	Main	BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	10	18.00	Replace	me
				Final Spare Part Cost						Final Sur Total	7,843.70	

One Time Key In	Main	Portion	Material Number	SMRT Recommendation	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval Check	Remarks
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	234.70	234.70	25.00	176.02	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check	?
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check	?
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	208.10	208.10	10.00	187.29	Replace	0	0	Check	?
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	?
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Check	?
One Time Key In	Main			BUMPER SEAL, RR RH	1	74.40	74.40	25.00	55.80	Replace	0	0	Check	?
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	93.90	93.90	25.00	70.43	Replace	1	70.43	Replace	scr✓
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	155.40	155.40	25.00	116.55	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			BUMPER LIP REAR	1	301.90	301.90	25.00	226.42	Replace	1	226.4	Replace	scr✓
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	586.10	586.10	25.00	439.58	Replace	0	0	Check	?
One Time Key In	Main			UNDER COVER RR SHIELD	1	66.10	66.10	25.00	49.57	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			HORN ASSY, HIGH	1	145.90	145.90	10.00	131.31	Replace	0	0	Not Give	X ₁₁
One Time Key In	Main			HORN ASSY, LOW	1	145.90	145.90	10.00	131.31	Replace	0	0	Not Give	X ₁₁

One Time Key In	Main			HEAD LAMP LH	1	1,075.40	1,075.40	10.00	967.86	Replace	0	0	Check	?
One Time Key In	Main			HEAD LAMP RH	1	1,075.40	1,075.40	10.00	967.86	Replace	1	967.8	Replace	scr✓
One Time Key In	Main			TUBE & ACCESSORY	1	830.50	830.50	25.00	622.88	Replace	0	0	Not Give	X ₁₁
						Total Spare Part Cost			44,126.99			Surveyor Total	7,843.70	
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,839.70	1,839.70	25.00	1,379.78	Replace	1	1,379	Replace	bt✓
						Lump Sum Discount (%)			20.00			Lump Sum Dis (%)	0	
						Final Spare Part Cost			35,301.59			Final Sur Total	7,843.70	

One Time Key In	Main	Portion	Material Number	HOSE SUB-ASSY DISCHARGE	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Replace	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval Check	Repair/Replace	Remarks	
One Time Key In	Main			A/C CONDENSER	1	1,695.90	1,695.90	25.00	1,271.93	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			HOSE SUB-ASSY SUCTION	1	534.40	534.40	25.00	400.80	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			RADIATOR ASSY UPPER	1	888.20	888.20	25.00	666.15	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			HOSE, INVERTER NO.1	1	104.70	104.70	25.00	78.53	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			HOSE, INVERTER COOLING NO.5	1	164.70	164.70	25.00	123.52	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			RADIATOR ASSY	1	2,245.70	2,245.70	25.00	1,684.27	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			CUSHION, RADIATOR (2 PCS)	2	14.80	29.60	25.00	22.20	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			SUPPORT RADIATOR, LH	1	23.40	23.40	25.00	17.55	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			SUPPORT RADIATOR, RH	1	72.00	72.00	25.00	54.00	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			SUPPORT, RADIATOR (2 PCS)	2	24.80	49.60	25.00	37.20	Replace	Replace	2	37.20	Replace	Replace	✓	
One Time Key In	Main			RADIATOR LOWER SUPPORT	1	1,004.70	1,004.70	25.00	753.53	Replace	Replace	0	0	Not Give	Not Give	Xm	
One Time Key In	Main			RADIATOR HOSE LOWER	1	56.00	56.00	25.00	42.00	Replace	Replace	0	0	Not Give	Not Give	Xm	
One Time Key In	Main			RADIATOR TOP HOSE NO 1	1	56.00	56.00	25.00	42.00	Replace	Replace	0	0	Check	Check	?	
One Time Key In	Main			RADIATOR HOSE BYPASS NO.1	1	49.30	49.30	25.00	36.97	Replace	Replace	0	0	Not Give	Not Give	Xm	
One Time Key In	Main			RADIATOR HOSE BYPASS NO.2	1	38.30	38.30	25.00	28.72	Replace	Replace	0	0	Not Give	Not Give	Xm	
One Time Key In	Main			RADIATOR HOSE BYPASS NO.3	1	49.30	49.30	25.00	36.97	Replace	Replace	0	0	Not Give	Not Give	Xm	
One Time Key In	Main			RADIATOR HOSE BYPASS NO.4	1	49.30	49.30	25.00	36.97	Replace	Replace	0	0	Not Give	Not Give	Xm	
One Time Key In	Main			INVERTER BRACKET TRAY	1	330.80	330.80	25.00	248.10	Replace	Replace	0	0	Not Give	Not Give	Xm	
One Time Key In	Main			INVERTER RADIATOR CUSHION	1	7.20	7.20	25.00	5.40	Replace	Replace	0	0	Not Give	Not Give	Xm	
						Total Spare Part Cost				44,126.99			0	0	Not Give	Not Give	Xm
						Lump Sum Discount (%)				20.00			0	0	Not Give	Not Give	Xm
						Final Spare Part Cost				35,301.59			0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give	Not Give	Xm
													0	0	Not Give		

One Time Key In	Main	Portion	Material Number	INVERTER W CONVERTER Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COOLANT (ADD QTY)	1	12.32	12.32	0.00	12.32	Replace	1	12.32	Replace	✓
One Time Key In	Main			COOLANT RESERVE TANK	1	521.40	521.40	25.00	391.05	Replace	0	0	Check	?
One Time Key In	Main			FAN SHROUD	1	321.40	321.40	25.00	241.05	Replace	0	0	Check	?
One Time Key In	Main			FAN SHROUD TOP	1	131.50	131.50	25.00	98.63	Replace	0	0	Check	?
One Time Key In	Main			FAN BLADE	1	236.90	236.90	25.00	177.68	Replace	0	0	Check	?
One Time Key In	Main			FAN BLADE NO.2	1	305.50	305.50	25.00	229.13	Replace	0	0	Check	?
One Time Key In	Main			FAN MOTOR NO.1	1	708.40	708.40	10.00	637.56	Replace	0	0	Check	?
One Time Key In	Main			FAN MOTOR NO.2	1	708.40	708.40	10.00	637.56	Replace	0	0	Check	?
One Time Key In	Main			COVER CYLINDER	1	218.10	218.10	25.00	163.57	Replace	0	0	Not Give	Xn
One Time Key In	Main			INLET ASSY, AIR	1	262.20	262.20	25.00	196.65	Replace	0	0	Not Give	Xn
One Time Key In	Main			AIR CLEANER ASSY	1	1,234.80	1,234.80	25.00	926.10	Replace	1	926.1	Replace	Xca ✓
One Time Key In	Main			WIRE, ENGINE ROOM	1	6,693.70	6,693.70	10.00	6,024.33	Replace	0	0	Not Give	Xn
One Time Key In	Main			WIRE, ENGINE ROOM, NO.2	1	256.40	256.40	10.00	230.76	Replace	0	0	Not Give	Xn
One Time Key In	Main			ENGINE MOULDING BRACKET, FRONT	1	99.90	99.90	25.00	74.93	Replace	0	0	Not Give	Xn
One Time Key In	Main			ENGINE MOULDING FRT	1	260.00	260.00	25.00	195.00	Replace	0	0	Not Give	Xn
One Time Key In	Main			END PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Not Give	Xn
One Time Key In	Main			SPARE TYRE PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Not Give	Xn
One Time Key In	Main			TAILGATE ASY	1	1,260.70	1,260.70	25.00	945.53	Replace	1	945.5	Replace	bt ✓
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	33.60	33.60	25.00	25.20	Replace	1	25.20	Replace	✓
Total Spare Part Cost										44,126.99		Surveyor Total 7,843.70		
Lump Sum Discount (%)										20.00		Lump Sum Dis (%) 0		
Final Spare Part Cost										35,301.59		Final Sur Total 7,843.70		

One Time Key In	Main	Portion	Material Number	TAILGATE DOOR GLASS MOULDING, LH Part Name	Qty	List Price 1,273.10 Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Replace	1	Surveyor Final Price(\$)	Surveyor Approval Replace	Remarks
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,273.10	1,273.10	25.00	954.82	Replace	0	0	Not Give	Xnn
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	33.60	33.60	25.00	25.20	Replace	1	25.20	Replace	me
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	33.60	33.60	25.00	25.20	Replace	1	25.20	Replace	me
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	827.50	827.50	25.00	620.63	Replace	0	0	Not Give	Xnn
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	31.30	31.30	25.00	23.48	Replace	1	23.48	Replace	me
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	22.30	22.30	25.00	16.73	Replace	1	16.73	Replace	me
One Time Key In	Main			TROUGH, BACK DOOR	1	126.80	126.80	25.00	95.10	Replace	0	0	Not Give	Xnn
One Time Key In	Main			SEALANT W/SCREEN (3PCS)	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	me
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH (2 PCS)	2	61.20	122.40	25.00	91.80	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAILGATE DOOR STAY LH	1	253.40	253.40	25.00	190.05	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAILGATE DOOR STAY RH	1	253.40	253.40	25.00	190.05	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAILGATE DOOR LOCK	1	631.90	631.90	10.00	568.71	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAILGATE LOCK, COVER	1	20.70	20.70	25.00	15.52	Replace	0	0	Not Give	Xnn
One Time Key In	Main			STRIKER, BACK DOOR	1	55.80	55.80	25.00	41.85	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	402.50	402.50	25.00	301.88	Replace	1	301.8	Replace	me
One Time Key In	Main			EMBLEM REAR	1	68.70	68.70	25.00	51.53	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	574.80	574.80	25.00	431.10	Replace	0	0	Not Give	Xnn
One Time Key In	Main			NAME PLATE (HYBRID)	1	59.20	59.20	25.00	44.40	Replace	1	44.40	Replace	me
One Time Key In	Main			NAME PLATE (PRUIS)	1	69.40	69.40	25.00	52.05	Replace	0	0	Not Give	me
Total Spare Part Cost										44,126.99		Surveyor Total		7,843.70
Lump Sum Discount (%)										20.00		Lump Sum Dis (%)		0
Final Sur Total										7,843.70		Final Sur Total		7,843.70

One Time Key In	Main	Portion	Material Number	Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval Not Give	Remarks
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	Xnn
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	Xnn
One Time Key In	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xnn
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP LH	1	618.60	618.60	10.00	556.74	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	35.20	35.20	25.00	26.40	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP RH	1	618.60	618.60	10.00	556.74	Replace	0	0	Not Give	Xnn
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	35.20	35.20	25.00	26.40	Replace	0	0	Not Give	Xnn
Standard	Main			WINDSCREEN FRT	1	1,543.80	1,543.80	25.00	1,157.85	Replace	0	0	Not Give	replace can ✓
Standard	Main			WINDSCREEN MOULDING FRT	1	57.60	57.60	25.00	43.20	Replace	1	0.00	Replace	✓
Standard	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	0.00	Replace	✓
Total Spare Part Cost										44,126.99	Surveyor Total		7,843.70	
Lump Sum Discount (%)										20.00	Lump Sum Dis (%)		0	
Final Spare Part Cost										35,301.59	Final Sur Total		7,843.70	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,014.00	600	
2	Main	TO REPAIR REAR PORTION	1,014.00	400	
Total:			2,028.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT HOOD	378.00	200	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	378.00	200	

Total:

2,430.00

1,000.00

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO RESPRAY TAIL GATE	378.00	200	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0 <i>Xan</i>	
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0 <i>Xan</i>	
7	Main	TO RESPRAY REAR PANEL	180.00	0 <i>Xan</i>	
8	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			2,430.00	1,000.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0 ?	receipt
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60	
4	Main	TO TOP UP A/C GAS	120.00	80	
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
7	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
8	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Xan</i>	
10	Main	TO CONDUCT RADIATOR PRESSURE CHECK	120.00	0 <i>Xan</i>	
11	Main	TO REMOVE / REFIT WINDSCREEN	120.00	120.00	
12	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	450.00	450.00	
Total:			1,962.88	1,266.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	35,301.59	7,843.70
Total Labour Cost	2,028.00	1,000.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spray Painting	2,430.00	1,000.00
Other	1,962.88	1,266.88
Overall Total	41,722.47	11,110.58
Lump Sum Repair Option	☐	☒
Lump Sum Total	41,700.00	11,100.00
Surveyor Approved Amount		11,100.00
No of Repair Days*	10	8
Remarks		lump sum repair / resurvey after repair request for NBV
Surveyor Name		Rasul
Signature		
Survey Date	05/09/2022	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHD6337Z
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6576689
Chassis No.:	JTDKN36U905767337
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	05 Feb 2016
First Registration Date:	05 Feb 2016
Transfer Count: -	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2024
PARF Rebate Amount:	\$3,250.00
COE Expiry Date:	04 Feb 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$43,040.00
COE Rebate Amount:	\$7,596.00
Total Rebate Amount:	\$10,846.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Sep 2022

OK