

SG735E.

TP Budget 2.1.1.

Toyota Provia 2362CC.

Xiao Chen

JTEGD52M20A019445

Rear Bumper	Behind	685.10 ✓
Rear Bumper	Cups. New	30(SN) ✓
Rear Bumper	Side Holder x 02 New	60.2 x 2 = 120.40 ✓
Rear Bumper	Reflector x 02 ²¹⁺ used	49.7 x 2 = 99.40 ^{49.70}
Rear Bumper	Low Cover. Behind	43.20 ✓
Reverse Sensor	Behind	280(SN) 200(SN)
Rear End Panel	Purple	609.70 +
Rear End Panel	Top Garnish. 2	281.10. +
Rear End Panel	Top Garnish Clips ^{New}	20(SN) +
Rear End Panel	Sealant. ✓	60(SN) +

898.40 S.N: 230

67380.

SGZ35E.

Panel Beating

~~700~~ 400

Spray Painting.

~~600~~ 400

Wiring.

~~50~~ 30

To spray tuff coat

~~150~~ 40

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~900~~ 150. 40

Total: 1863.00

L/S: 1.5/1c.

03 Days.

3978.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: