

ASS. REC. BY:

REF:

C12 / 22 008835/kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBK 1569M

Yr Regn:

01, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer 114 CDI

c.c

2143

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

82450

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDF 44760323 596929

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / R / STD A / R / or

Tyre Size:

F:

215/60R16

Continental

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

22/8/22

D.O.I.

8/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

: Fixing

: Others

TOTAL

Report Format :

ump Sum / I.B.I: (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : XD8158X

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2019

ACCIDENT DATE : 22/08/2022

TP VEH REG NO : XD8158X

ESTIMATE

NO : QUOT202209-000003(00)

DATE : 01/09/2022

POLICY NO : 999995580

VEH REG NO : GBK1569M

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323596929

ENGINE NO : 65195035068888

Estimate Repair Cost to Vehicle No : GBK1569M

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Bonnet	1	1,670.00	1,670.00 ✓
2 Bonnet lock	1	138.00	138.00 ✓
3 Bonnet hinge - RH / LH	2	86.00	172.00 X
4 Front grille centre logo	1	158.00	158.00 ✓
5 Brace panel	1	98.00	98.00 ?
6 Headlamp assy - RH / LH	2	780.00	1,560.00 2x
7 Support Panel	1	420.00	420.00 ?
8 Support panel top bracket - RH / LH	2	24.00	48.00 ?
9 Support panel top garnish	1	76.00	76.00 ✓
10 Front bumper	1	870.00	870.00 ✓
11 Front bumper reinforcement	1	720.00	720.00 ?
12 Front bumper side retainer - RH / LH	2	74.00	148.00 X
13 Air-con condenser	1	650.00	650.00 ?
14 Air-con condenser frame	1	120.00	120.00 ?
			6,848.00
		Less 10%	684.80
			6,163.20
LABOUR			
15 To remove and refit air-con condenser, radiator and refit air-con gas	1	150.00	150.00 ?
16 To panel beat and straighten front fender, front chassis frame, including replacement of parts and realign where necessary, to refit and adjust the same	1	1,000.00	1,000.00 ?
17 To check and rectify wiring system	1	80.00	80.00 201
18 To putty and spray paint on affected areas	1	1,000.00	1,000.00 250
19 To reset and reprogram headlamp fault code	1	350.00	350.00 ?
20 To apply rust proofing on replaced and repaired panels	1	120.00	120.00 301
21 To supply and paste decal on bonnet	1	400.00	400.00 ?
			3,100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

TOTAL S\$ 9,263.20
ADD GST @ 7% 648.42
GRAND TOTAL S\$ 9,911.62

SINGAPORE DOLLAR NINE THOUSAND NINE HUNDRED ELEVEN AND CENTS SIXTY-TWO ONLY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/08/2022 15:59 (SGT)
Reported by	Driver
Date of Accident	22/08/2022 12:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	OUTSIDE NO. 4, SUNGEI KADUT STREET 3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBK1569M
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Company Reg No	1XXXXX778Z
Email Address	derrick.lee@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Vito
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	3199

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	999995580

DRIVER

Name of Driver	LEONG TUAN CHUN
NRIC No	SXXXX243F
Date Of Birth	19/06/1993
Occupation	Outdoor


Describe Circumstances of the Accident

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE SAID LOCATION AND WENT FOR MY DELIVERY. WHEN I CAME BACK TO MY VEHICLE, IT WAS HIT BY A REVERSING VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Declaration

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed By Reporting Officer
Hashim Bin Kamari

Witnessed by Reporting Centre
Personnel