



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300235

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/01/2023
Reference CC6/CTI22008838/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 4002P
Insured Veh. GBF 2892Z
Claim No. SNM22D206340/C02
Policy No. DMCVSNW00095262202
Accident Date 05/09/2022
Inspection Date 07/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22008838/Kpa3q2 Date: 12/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 2892Z	Veh. Inspected	SLZ 4002P	
Policy No.	DMCVSNW00095262202	Coverage (\$)	0.00	
Claim No.	SNM22D206340/C02	Excess (\$)	0.00	
Assign From		Assign Date	07/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PREVIA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTEGD56M207161303	Colour	METALLIC PEARL WHITE	
Odometer	97886 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	9 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	9 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2022	Inspection Date	07/09/2022	
Survey held at	HWA SENG SPRAY PAINTING PTE LTD 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 4002P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	644.90	644.90
1	END PANEL	BENT	817.00	648.10
2	REAR BUMPER RETAINERS @\$62.50	N/S DISTORTED	125.00	62.50
2	REAR BUMPER BRACKETS @\$43.80	TO REPAIR SEE LABOUR	87.60	-
1	TAILGATE LOWER LOCK	TO REPAIR SEE LABOUR	530.50	-
2	REAR BUMPER SPONGE @\$85.90	CRACKED (1PC ONLY)	171.80	85.90
2	REAR BUMPER SENSORS @\$393.60	SERVICEABLE	787.20	-
1	END PANEL GARNISH	BUCKLED	229.40	229.40
1	LOGO EMBLEM	NECESSARY	52.20	52.20
1	EMBLEM 'PREVIA'	NECESSARY	72.10	72.10
	LESS 25% DISCOUNT		-879.43	-448.78
			2,638.27	1,346.32
	<u>LABOUR</u>			
	PANEL KNOCKING. INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKETS AND TAILGATE LOWER LOCK.		900.00	600.00
	SPRAY PAINTING.		900.00	660.00
	LABOUR TO REMOVE UPHOLSTERY.		180.00	60.00
	WIRE CHECKING.		80.00	20.00
			2,060.00	1,340.00
	GRAND TOTAL		4,698.27	2,686.32
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00

Report Ref No. CC6/CTI22008838/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 4002P

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 4002P

RE-INSPECTION

