

ASS. REC. BY:

REF:

C72/ 22008838/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 4002P Yr Regn: 04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Provi Wagon c.c. 2362Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 97886 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEG056M 207181303Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

Rear

R/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 5/9/22D.O.I. 7/9/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/9 11:30 @ 21506 CUBAN

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

HWA SENG SPRAY PAINTING PTE LD
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO.: 202017045G)
 TEL : 64533100
 FAX : 62669932

Date of Accident: 05/09/22

Your Insured

Vehicle No. GBF 2892Z

Not Withstand
 11 Lyr @ 2150/r
 Return After Pain

ESTIMATE REPAIR COSTS TO TOYOTA PREVIA REG. NO. : SLZ 4002 P

3 days

S\$

1pc	Rear Bumper		644.90	✓
1pc	End Panel	648.10	817.00	✓
2pcs	Rear Bumper Retainers	(\$62.50/pc)	125.00	✓
2pcs	Rear Bumper Brackets	(\$43.80/pc)	87.60	✗
1pc	Tailgate Lower Lock		530.50	✗
2pcs	Rear Bumper Sponge	(\$85.90/pc)	171.80	✗
2pcs	Rear Bumper Sensors	(\$393.60/pc)	787.20	✗
1pc	End Panel Garnish		229.40	✓
1pc	Logo Emblem		52.20	✓
1pc	Emblem 'PREVIA'		72.10	✓

3517.70

Less : 25%

879.43

2638.27

LABOUR & MISC CHARGES

Panel Knocking	900.00	600
Spray Painting	900.00	600
Labour to Remove Upholstery	180.00	60
Wire Checking	80.00	20

TOTAL

4698.27

HWA SENG SPRAY PAINTING PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date: