

TP AXA.
Xiao Chen

SMP3395C 2019 Sept.
Honda Freed Hybrid. 1496 cc
GB 71080217.

Rear Number Plate.	behind	30(SN) ✓
Rear Number Plate Holder	behind	30(SN) ✓
Rear Number Plate Lamp x 02	MP m	50.1 x 2 = 100.20 +
Rear Bumper	Distorted	829.40 ✓
Rear Bumper Clips.	m	30(SN) ✓
Rear Bumper Side Holder x 02	m	32.4 x 2 = 64.80 ✓
Rear Bumper Reflector x 02	MP m	90.1 x 2 = 180.20 +
Reverse Sensor	Damaged	280(SN) 200(SN)
Rear End Panel	Distorted	509.40 ✓
Rear End Panel Inner	Distorted	351.20 ✓
Rear End Panel Top Garnish	behind	208.40 ✓
Rear End Panel Top Garnish Clips.	m	20(SN) ✓
Rear End Panel Sealant.	m	60(SN) ✓

SMP 3395C

~~661.10~~

Tailcap x 02 RH Ant

661.1 x 2 = 1322.20.

Tailgate Distorted

1115.90 ✓

Tailgate Lock Dryd

185.90 ✓

Tailgate Weatherstripe. ut

241.70 ✓

Tailgate Chrome Moulding. H

315.80 X

Tailgate Chrome Moulding Clips. RH

20(SW) X

Tailgate Lower Trim Board Auld

288.90 ✓

Tailgate Lower Trim Board clips. RA

30(SW) ✓

Tailgate Reflector x 02 RH

368.2 x 2 = 736.40 X

Tailgate Surround Moulding. RH

150(SW) 100(SW)

Tailgate Glass Moulding. } RH

85.90 ✓

Tailgate Glass Sealant.

60(SW) ✓

Tailgate Liner Holder Dehd

55.10 ✓

Honda Logo. Z

38.40 ✓

Freed Emblem. NA

56.90 ✓

Hybrid Emblem.

59.40 ✓

Gecko Sticker. ✓

50(SW) 30(SW)

Smp 3395c

Reer Camera.

new

480(SN).X

Reer Fender Inner Trim Board

Dehnd

424.1X2=828.20

Reer Fender Inner Trim Board Clips.

new

60(SN) ✓

Floor Panel

Reps

1578.20.X

Floor Panel Insulator

new

~~300(SN)~~. 200(SN)

Floor Panel Top Mat.

new

588.20.X

Floor Panel Undercover

Dehnd

241.20 ✓

Floor Panel Undercover Clips.

new

30(SN) ✓

Reer Exhaust Pipe.

2

~~688~~. 10 X

Reer Exhaust Pipe Mounting.

NP
new

38.20.X

Reer Exhaust Heat Shield.

145.40.X

SMP 3395 C

Front Number Plate.	2 ^{HP} _{in}	30(SN) X
Front Number Plate Holder		30(SN) X
Front Bumper.	Delhd	986.40. ✓
Front Bumper Clips.	^{HP} _{in}	30(SN) ✓
Front Bumper Side Holder x 02		38.6 x 2 = 77.20 X
Front Bumper Reinforcement.	^{HP} _{in}	295.80 X
Front Bumper Lower Grille	^{HP} _{in}	165.80 X
Front Grille	anhd	690.40 ✓
Front Grille clips.	2 ^{HP} _{in}	20(SN) ✓
Front Grille Logo.		78.10. ✓
Front Grille Chrome Molding	^{HP} _{in}	168.40 ✓
Handcup x 02	^{HP} _{in}	1740 x 2 = 3480. X
Handcup lower Bracket x 02.		60.5 x 2 = 121. ✓
	RH Cnhd	60.50

SMP 3395 C.

Panel Beating (Front)	400 200
Spray Painting (Front)	400 200
Wiring (Front)	50 30
Panel Beating (Rear)	1400 1000
Spray Painting (Rear)	1400 900
Wiring (Rear)	50 30
To spray full coat.	180 80
To remove reverse sensor	100 50
To remove rear camera.	100 50
To remove video recorder.	100 50
To remove upholstery.	150 60
To transfer tailgate glazing	180 120
To transfer tailgate fittings.	180 80

SMP 33 95C.
To remove exhaust pipe.

150 X.

List: 780560 Labor: 2850
Len 20% 624440 total: 996440
S.N: 870 A/s: 7.9k.
09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: