



AKA AUTO PTE LTD  
 25 KAMI BUKIT ROAD #05-36, #05-37  
 SYNERGY @ KB  
 S417800  
 H: 81880754

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Prices are subject to confirmation  
 This survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

ROC: 2017000881

Signature:

Date:

TP MSLG  
 Hui Zong.

9/8/2022

ESTIMATED REPAIR CHECKLIST

TO :	VEHICLE REGISTRATION NO.: SKV7401J
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: MAZDA / 5
CLAIM TYPE : OD PARTY CLAIM	CHASSIS NUMBER: JM6CW1071G0122295
ACCIDENT DATE/TIME :	CONTACT PERSON :

PARTS	QTY	PER UNIT	PRICES
1 REAR BUMPER <i>blend</i>	1	\$ 962.40	\$ 962.40
2 REAR BUMPER SIDE HOLDER <i>RT 2nd</i>	2	\$ 48.10	\$ 96.20
3 REAR BUMPER REINFORCEMENT <i>Revised</i>	1	\$ 237.40	\$ 237.40
4 REAR BUMPER REFLECTOR <i>seen</i>	2	\$ 65.10	\$ 130.20
5 REAR END PANEL <i>Revised</i>	1	\$ 542.30	\$ 542.30
6 REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 181.20	\$ 181.20
7 TAILLAMP <i>Could RT</i>	2	\$ 593.40	\$ 1,186.80
8 TAILGATE <i>Revised</i>	1	\$ 1,637.00	\$ 1,637.00
9 TAILGATE LOCK <i>seen</i>	1	\$ 286.90	\$ 286.90
10 TAILGATE WEATHERSTRIPE <i>seen</i>	1	\$ 295.40	\$ 295.40
11 TAILGATE GLASS MOULDING <i>seen</i>	1	\$ 168.00	\$ 168.00
12 MAZDA LOGO	1	\$ 48.90	\$ 48.90
13 MAZDA 5 WORDING <i>seen</i>	1	\$ 45.60	\$ 45.60
14 SKYACTIV EMBLEM	1	\$ 49.10	\$ 49.10
15 TOOLS TRAY <i>seen</i>	1	\$ 404.80	\$ 404.80
		<b>Sub total</b>	SUBTOTAL : \$ 6,272.20
		Less 20%	LESS 20% : \$ 995.24
		<b>Total List</b>	<b>PARTS TOTAL : \$ 5,276.96</b>

*2970.30*  
*Len 20%: 2376.24*  
*Tailgate lamp RH. cut ✓ 395*

SPECIAL NETT	QTY	PER UNIT	PRICES
1 REAR BUMPER CLIPS <i>seen</i>	1 SET	\$ 50.00	\$ 50.00
2 REVERSE SENSOR <i>Revised</i>	1 SET	\$ 280.00	\$ 280.00
3 REAR END PANEL TOP GARNISH CLIPS <i>seen</i>	1 SET	\$ 20.00	\$ 20.00
4 REAR END PANEL SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00
5 TAILGATE GLASS SEALANT <i>Not seen</i>	1 SET	\$ 60.00	\$ 60.00
6 MAZDA WORDING (GOLD) <i>seen</i>	1	\$ 60.00	\$ 60.00
		<b>Sub total</b>	<b>S/N TOTAL : \$ 530.00</b>

*370*

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 1,200.00	500
2 SPRAY PAINTING	\$ 1,000.00	600
3 WIRING	\$ 50.00	30
4 TO SPRAY TUFF COAT	\$ 150.00	60
5 TO REMOVE REVERSE SENSOR	\$ 100.00	50
6 TO REMOVE UPHOLSTERY	\$ 150.00	40
7 TO TRANSFER TAILGATE FITTINGS	\$ 150.00	+
8 TO REMOVE TAILGATE GLASS	\$ 180.00	+
<b>LABOR TOTAL :</b>		<b>\$ 2,980.00</b>

*1280*

total: 4026.24  
 H/S: 3.2K  
 After H/S 08/09/22  
 04 days