



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Ref: CS3/ASM22008851/Gcy3

Date: 08/09/2022

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 6300P	Veh. Inspected	SLS 2823L
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04ALQ	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	08/09/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/09/2022	Inspection Date	09/09/2022
Survey held at	2 KAKI BUKIT AVENUE 2 #02-31 KAKI BUKIT AUTOHUB Si		
Repairer	CHENG CHUAN MOTOR SERVICES		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
