

ASS. REC. BY:

REF:

CT2 / 2200-8852 / Kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2-3 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SMY 4250H

Yr Regn:

08, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra c.c 1391

Colour

M. L Purple

A/C: Insured / Std / NI / NA

Sp. Reading

51810

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH0841CHJU 72827

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / B/Rlm / STD A/Rlm or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

3/19/22

D.O.I.

9/9/2022

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F. P. S.

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

China Taiping Insurance (Singapore) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Motor Claim Department

NOT AUTHORIZED
1.3.1. 11/12/87
2-3 days

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SMY4250H

MODEL ELANTRA AD 1.6 GLS AT (AMS)

POLICY NO :

CHASSIS NO : KMHD841CMJU725827

Date: 09/08/2022

Page : 1 of 2

DATE / TIME OF ACCIDENT: 03/09/2022 Time: 1115Hrs at WOODLANDS CHECKPOINT
THIRD PARTY VEHICLE NO: SLN3894B

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 REAR BUMPER	1	459.40		459.40 7
2 REAR BUMPER BLACK DIFFUSAL	1	250.10		250.10 7
3 REAR REINFORCEMENT BAR	1	303.70		303.70 7
4 BOOT TRUNK	1	1,840.00		1,840.00
5 REAR FENDER RH	1	1,856.60		1,856.60
6 REAR BRAKE LIGHT RH	1	388.00		388.00
7 REAR BOOT BRAKE LIGHT RH	1	298.80		298.80
8 REAR BOOT BRAKE LIGHT LH	1	298.80		298.80
9 SPARE TYRE PANEL	1	878.30		878.30
10 ELANTRA EMBLEM	1	48.80		48.80
11 HYUNDAI LOGO EMBLEM	1	28.10		28.10
12 ELITE EMBLEM	1	35.00		35.00
13 REAR REFLECTOR STRIP RH	1	28.30		28.30
14 REAR BUMPER RETAINERS	2	40.80		81.60
15 BOOT INNER RUBBER SEAL	1	59.80		59.80
16 REAR END PANEL	1	454.70		454.70
17 REAR END GANISH	1	60.00		60.00

Sub-Total: 7,370.00
Parts after 20% discount 1,474.00
Total Parts : 5,896.00

Special Nett Items

1	Anti-rust coating	2	80.00	~	160.00	X
2	REVERSE SENSOR SET	1	350.00		350.00	?
3	REAR PANEL SEALANT	1	150.00	~	150.00	X
4	REVERSE CAMERA SET	1	350.00	~	350.00	X
5	REAR NUMBER PLATE WITH HOLDER	1	120.00	~	120.00	X
6	BODY WRAPS	1	1,500.00	(Bill)	1,500.00	2500?
7	BODY KIT RER DIFFUSAL	1	800.00	~	800.00	?

Total Parts: 3,430.00

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. (Front)	1,000.00	2000
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,000.00	?
3	Provide skill labour to disconnect and check electrical wiring	100.00	100
4	Remove and replacement of bumper sensor	100.00	?
5	Remove and reinstall inner trim garnish to facilitate repair	200.00	X

Total Labour:

Total Parts & Labour:
GST 7%
Grand Total:

2,400.00
11,882.32
831.76
12,714.08

Estimate Repair Duration

10 days

2-3

ACCIDENT VEHICLE OF : SMY4250H

Page : 2 of 2

Remark Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Ninja Lo

Survey attended by:

Name : _____

Company : _____

Date : _____

Time : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/09/2022 17:22 (SGT)
Reported by Both
Date of Accident 03/09/2022 11:15 (SGT)
Exact Location of Accident 21 Woodlands Crossing, Singapore 738203
Additional Location Information WOODLANDS CHECKPOINT
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMY4250H

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NG KONG KIAT LUCAS
NRIC No SXXXX816C
Email Address LUCASNKJ21@GMAIL.COM
Mobile Phone No (Phone) +65-89504757
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Hyundai
Model Elantra
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1599

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number MQ005625

DRIVER

Name of Driver NG KONG KIAT LUCAS
NRIC No SXXXX816C
Date Of Birth 26/07/1997
Occupation Indoor

SKETCH PLAN

A-) SMY4250H

B-) SLN3894B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3/09/22, I was queuing up for my turn at woodlands checkpoint. Suddenly, I felt an impact from vehicle B on the rear of my vehicle. My rear bumper is damaged and my rear diffuser is broken.

DECLARATION

I hereby declare that the information provided is true and correct.

Signature of the driver of the vehicle involved in the accident

Signature of the driver of the vehicle involved in the accident

Signature of the driver of the vehicle involved in the accident