

ASS. REC. BY:

REF:

CT2/22008854/1ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s TPR

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 03/24 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKU 993314 Yr Regn: 03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios c.c. 1497

Colour: Orange Red A/C: Insured / Std / NI / NA

Sp. Reading: 209373 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR05314Y9305097310

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 0 mm

L/Bal. 0 mm

D.O.A. 7/19/22

Rear

R/Bal. 0 mm

L/Bal. 0 mm

D.O.I. 8/9/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or OLS RM & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>GIA & En not ready</u>
<u>13/9</u>	<u>11 Rm @ 4000 Cash</u>

Date/Time, File Pass to?

: Prell. Report
 : Final Report

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

) S + RS. SI

) Fix Ins

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

NOT Notified
11 Sep @ 4000h
Resurvey After Paint
5 days

Date : 8 Sep 2022

QUOTATION - THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (SINGAPORE)PTE LTD

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 8 Sep 2022

VEH. No : SKU 9933 H / VIOS

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : NTUC INCOME

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : SMS 2199 T			

1	FRONT RH DOOR	REPAIR	
1	FRONT RH FENDER	\$ <i>R</i> 386.80	✓
1	FRONT RH FENDER UNDERSHIELD <i>141</i>	\$ <i>DIY</i> 280.00	✓
1	FRONT RH FENDER EMBLEM <i>48</i>	\$ <i>re</i> 120.00	✓
1	FRONT RH FENDER INNER PANEL	REPAIR	
1	FRONT RH W/SCREEN SIDE PILLAR	REPAIR	
1	FRONT SUPPORT PANEL	\$ <i>R</i> 980.00	X
1	BONNET	REPAIR	
1	HEADLAMP RH <i>525</i>	\$ <i>CMT</i> 620.00	✓
1	HEADLAMP LOWER BRACKET RH	\$ <i>su</i> 180.00	X
1	FRONT BUMPER <i>425</i>	\$ <i>my CMT</i> 596.30	✓
1	FRONT BUMPER LOWER COVER RH	\$ <i>su</i> 280.00	X
1	FRONT BUMPER RETAINER RH	\$ <i>DIY</i> 181.45	✓
1	FRONT RH WHEELHUB	\$ <i>R</i> 388.50	✓
1	FRONT RH WHEEL BEARING } <i>275.10</i>	\$ <i>re</i> 298.60	✓
1	FRONT RH SUSPENSION } <i>393.70</i>	\$ <i>R</i> 522.30	✓
1	FRONT RH SUSPENSION TOP MOUNTING	\$ <i>su</i> 260.00	X
1	FRONT RH LOWER ARM	\$ <i>R</i> 378.50	✓
1	FRONT RH KNUCKLE ARM	\$ <i>R</i> 388.45	✓
1	FRONT RH STABILIZER BAR	\$ <i>re</i> 296.00	X
1	FRONT RH STABILZER BAR LINK	\$ <i>DIY</i> 168.00	✓
1	FRONT RH TIE ROD	\$ <i>su</i> 223.00	X
1	FRONT RH TIE ROD END	\$ <i>re</i> 165.00	X
1	FRONT RH DRIVE SHAFT <i>CR</i>	\$ <i>RD</i> 2,240.00	<i>COUSIN</i>
TOTAL PARTS :		\$ 8,952.90	
LESS 25%		\$ 2,238.23	
TOTAL LIST PARTS :		\$ 6,714.68	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TSR AUTOMOTIVE PTE LTD

160, SIN MING DRIVE . SIN MING AUTOCITY

06-15 SINGAPORE 575722

EMAIL : tsrteamworks2022@gmail.com . H.P 90030857 .

Date : 8 Sep 2022

QUOTATION - THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (SINGAPORE)PTE LTD

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 8 Sep 2022

VEH. No : SKU 9933 H / VIOS

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : NTUC INCOME

SPECIAL / NETT PARTS			
10	FRONT BUMPER CLIPS	\$	<i>me</i> 45.00 <i>✓</i>
10	FRONT RH FENDER UNDERSHIELD CLIPS	\$	<i>me</i> 45.00 <i>✓</i>
1	FRONT RIM RH	\$	<i>no</i> 800.00 <i>300\$</i>
1	FRONT TYRE RH	\$	<i>no</i> 400.00 <i>70\$</i>
TOTAL S/N PARTS :		\$	1,290.00
TOTAL PARTS PRICE :		\$	8,004.68
AMOUNT BRING FORWARD :		\$	8,004.68
Labour charges to repair replace accident affected body parts		\$	1,200.00 <i>500</i>
To check front wiring system, focus headlamp etc		\$	120.00 <i>20</i>
To check and replace front undercarriage		\$	300.00 <i>200</i>
To do anti rust for accident affected area		\$	120.00 <i>30</i>
To do computer wheel alignment before repair and after repair		\$	160.00 <i>60</i>
To do spray painting on accident affected area (inner and outer)		\$	1,200.00 <i>600</i>
TOTAL LABOUR :		\$	3,100.00
GRAND TOTAL PARTS & LABOUR :		\$	11,104.68

The Repaired of the following:
 - To do spray painting
 - To do body damaged parts during resurvey
 - To do anti rust subject to confirmation
 - To do computer wheel alignment before repair and after repair
 - To do spray painting on accident affected area (inner and outer)
 - To do anti rust for accident affected area
 - To check and replace front undercarriage
 - To check front wiring system, focus headlamp etc
 - Labour charges to repair replace accident affected body parts

Approved by Repaired