

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jonathan Lim
CLAIM DEPARTMENT
DID : 66547606
FAX : 66547540

Date : 08/09/2022

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION**

Attn : **Motor Claim Department** FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 22/08/2022

Vehicle No : GBC-3306-J Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS Excess : 4,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	FRONT BUMPER / <i>ll</i>	670.60	
1	LH FRONT BUMPER LH RETAINER X <i>nn</i>	38.20	
10	BUMPER CLIPS / <i>mc</i>	45.00	
1	LH HEADLAMP LOWER GARNISH / <i>ll</i>	471.60	
	Sub Total	1225.40	
	Discount 10% On Parts	(122.54)	
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	400.00	<i>200</i>
	TO SPRAY PAINT ON AFFECTED PORTIONS	400.00	<i>100</i>
	TO CHECK AND RECONNECT NECESSARY WIRINGS	25.00	<i>X nn</i>

Date : 08/09/2022
 To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 ESTIMATION**
 Attn : **Motor Claim Department** FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : 1 Accident Date : 22/08/2022
 Vehicle No : GBC-3306-J Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS Excess : 4,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Sub Total		825.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect (damaged part/s) during resurvey
- To provide written confirmation
- To estimate on "Without Prejudice" basis
- To provide estimate to the insured
- To provide estimate to the surveyed and
- To provide estimate to the insurance Company

Accepted by repairer
 Signature:
 Date:

1,927.86

Remarks:

*2 Days
 Lumpsum Repair*

SUB TOTAL
GST 7.0 % 134.95
TOTAL 2,062.81

Surveyor's name: Gene Ai of - 8288 0282

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 8/9/2022