



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile **CS3/ASM22002707/Gcy3-1**

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~CS3/ASM22002707/Gcy3~~
Date: ~~24/03/2022~~ 08/09/2022
Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLZ 810A	Veh. Inspected	SJN 6673B
Policy No.		Coverage (\$)	0.00
Claim No.	S2M03WJU	Excess (\$)	0.00
Assign From	KHONG LYNN	Assign Date	24/03/2022 08/09/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/03/2022	Inspection Date	24/03/2022
Survey held at	KING'S AUTO REPAIR & SERVICE PTE LTD 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.