



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHARACTERIST LLC 190 MIDDLE ROAD #15-01A FORTUNE CENTRESINGAPORE 188979		Ref: CS/LAW22008861/Kny3e2 Date: 10/11/2022 Code: L057	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	GBG 4715J	Veh. Inspected	SLT 8181K
Policy No.		Coverage (\$)	0.00
Claim No.	GCW.PD.6262.2021	Excess (\$)	0.00
Assign From	f. DANIEL GOH	Assign Date	08/09/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PREVIA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTEGD56M107152902	Colour	METALLIC GREY
Odometer	89143 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	9 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	9 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	02/06/2021	Inspection Date	13/09/2022
Survey held at	JP CONCEPTZ PTE LTD 160 SIN MING DRIVE #07-11 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	