

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22008863/UYA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070121134
Claimant Vehicle No :	SLG4140Z	Insured Vehicle No :	SGD880Y
Date of Loss:	03/09/2022	Nature of Claim:	TP
		Claim No:	3336086590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG4140Z	Engine No:	2ZRR951545
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU203535330
Reg. Date:	29/09/2016 (Man. Year: 2016)	Odometer:	263566 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Arivo 7 mm	Rear Left Side:	Arivo 7 mm
Front Right Side:	Arivo 7 mm	Rear Right Side:	Arivo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,815.50	3,079.50	3,736.00	54.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	800.00	1,640.00	67.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,255.50	3,879.50	5,376.00	58.08
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	9,255.50	3,100.00	6,155.50	66.51
+ GST 8.00/8.00% (S\$)	740.44	248.00	492.44	66.51
Nett Amount (S\$)	9,995.94	3,348.00	6,647.94	66.51
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
(S\$)		3,648.00		
Liabe Amount (50.00%) (S\$)		1,824.00		
+ Doc/Search Fee (S\$)		33.00		
Nett Liability (S\$)		1,857.00		

INSPECTION

Date of Assignment:	08/09/2022	
Date Inspected:	25/10/2022 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Distorted	879.00 FL	*879.00 FL
2	1		*FRT BUMPER SIDE RETAINER RH	Bent	45.00 FL	*45.00 FL
3	1		*FRT BUMPER SIDE DAYLIGHT RH	Cracked	321.00 FL	*321.00 FL
4	1		*FRT BUMPER DAYLIGHT COVER RH	Not fitted	52.00 FL	*- FL
5	1		*FRT BUMPER BRACKET RH	Not Necessary	52.00 FL	*- FL
6	1		*WIPER WASHER TANK	Not Necessary	345.00 FL	*- FL
7	1		*SIDE MIRROR RH	Not Necessary	698.00 FL	*- FL
8	1		*FRONT FENDER RH	Dented	698.00 FL	*698.00 FL
9	1		*FRONT FENDER EMBLEM HYBRID RH	Not Necessary	52.00 FL	*- FL
10	1		*FRONT FENDER COWLING RH	Torn	198.00 FL	*198.00 FL
11	1		*FRT LOWER ARM RH	Not Necessary	581.00 FL	*- FL
12	1		*FRT KNUCKLE ARM RH	Not Necessary	587.00 FL	*- FL
13	1		*FRT WHEEL BEARING RH	Not Necessary	198.00 FL	*- FL
14	1		*FRONT HEADLAMP RH	Cracked	1,125.00 FL	*1,125.00 FL
15	1		*REAR DOOR RH	Not Necessary	1,125.00 FL	*- FL
16	1		*REAR BUMPER	Not Necessary	798.00 FL	*- FL
17	1		*SET FRT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
18	1		*FRT FENDER INNERSHIELD CLIP SET LH	Not Necessary	50.00 FS	*- FS
19	1		*FRONT WHEEL HUB CAP RH	Not Necessary	100.00 FS	*- FS
20	1		*FRONT SPORTS RIM RH	Warped	800.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,754.00	3,896.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,938.50	816.50
Total Parts (\$)	6,815.50	3,079.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	100.00	20.00
2	R+R FRONT UNDERCARRIAGE	New	400.00	0.00
3	WHEEL ALIGNMENT	New	100.00	60.00
4	R+R FRT FENDER QUARTER GLASS RH	New	120.00	0.00
5	REALIGN HEADLAMP	New	120.00	0.00
6	LABOUR	New	600.00	320.00
7	SPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (S\$)			2,440.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >