

ASIS REC-8Y: Tauhin

REF: CC4/LR 2208865/TP 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$186K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFD 8888X

Yr Regn: 2021, Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota

C.C. 2487

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 13303

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STEADSBH 90J0007J

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/60R18

R: _____

(S) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at Borneo Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

____ S + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.A. (P) _____



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM <i>Longal</i> <i>Liability</i> <i>Check</i> <i>Mr. New Shun</i>				S1000020 / TPCLAIM		Mr Chow Weng Fatt 54 Jalan Riang Serangoon Park Singapore 359019 Mobile: 96478122			
				Document No. 0					
				Document Date 08/09/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2021	AXUH80R	ANXGB 1P	25/08/2021	SFD8688X	0	22035	69DS/SFD8688X		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEAD3BH90J000758		A25A0943780	60	Raymond Seah L M	--/--/----		0.00		--/--/----
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:YN7644B ACC DATE:07/09/2022 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM						✓ 30.00	
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						✓ 180.00	
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.						✓ 122.40	
4	B	BP-LAB2 TO REPLACE/REPAIR FRONT LH SIDE ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.						1440 2880.00	
5	B	BP-RES2 TO SPRAY PAINT ON FRONT LH SIDE ACCIDENT AFFECTED AREAS.						1770 2360.00	
6	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION						✓ 274.77	
7	1	T81185-48J10 UNIT, HEADLAMP L			1.00	7067.70		? 7067.70	
8	2	T52119-4D977 COVER, FR BUMPER			1.00	676.60		de 676.60	
9	3	T52134-48090 BRACKET, FR BUMPER, L			1.00	173.60		? 173.60	
10	4	T52536-48080 RETAINER, FR BUMPER L			1.00	108.70		? 108.70	
For & on behalf of				Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd				Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
								Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details						
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Mr Chow Weng Fatt						
		Document No. 0		54 Jalan Riang Serangoon Park Singapore 359019						
		Document Date 08/09/2022		Mobile: 96478122						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks			
2021	AXUH80R	ANXGB 1P	25/08/2021	SFD8688X	0	22035	69DS/SFD8688X			
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On			
JTEAD3BH90J000758		A25A0943780	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00			
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount		
11	5	T90467-05170 CLIP ^L			2.00	2.80		5.60		
12	6	T47749-33030 CLIP, PIN HOLD ^L			2.00	9.50		19.00		
13	7	T53879-33030 RETAINER, FR FENDER ^L			2.00	13.20		26.40		
14	8	T53802-48160 FENDER SUB-ASSY, FR ^L			1.00	1360.60		1360.60		
15	9	T53828-48060 PROTECTOR, FR FENDER ^L			1.00	99.30		99.30		
16	0	T75362-48080 PLATE, FR FENDER ^L			1.00	59.10		59.10		
Taufik 97495749 WIP 12/9/22 @ 1130 P/P using before paint 5 days taufik@lkhauto.com										
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company										
For & on behalf of		Customer's Signature		Charge Summary		Total				
Borneo Motors (Singapore) Pte Ltd						15,443.77				
		Please acknowledge receipt of vehicle		Parts		9,596.60		GST 7.00%	1,081.06	
				Labour		5,572.40				
				Sublet		274.77		Less		0.00
				Lubrication/Fluid		0.00				
				Others		0.00		Amount Due		16,524.83

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

FOR REFERENCE

Coating

INTERNAL INVOICE

Account Details			Account No.		Customer Details			
New vehicle preparation PDI ***** For use by BMS PDI *****			i0100001 / NEWVEHIC		Mr W F Chow 54 Jalan Riang Serangoon Park Singapore 359019			
			Document No. 38059469					
			Document Date 18/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	AXUH80R	ANXGB 1P	25/08/2021	SFD8688X	1	64456	69INT/SFD8688X	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEAD3BH90J000758		A25A0943780	00	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	M	D1068*-PLATINUM SHINEPRO						250.00
	*	PSPRO PDI LABOUR FOR PLATINUM SHINE PDI						
2	*	D1068D) Platinum Shine Glass Coating						
	*	PSPRO MAT PDI PLATINUM SHINE SET						
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 250.00	
			Please acknowledge receipt of vehicle		Parts	0.00	GST 0.00%	0.00
					Labour	0.00	Less	0.00
					Sublet	0.00		
					Lubrication/Fluid	0.00		
					Others	250.00	Amount Due	250.00

Customer Copy