

Reg No. : 196700086Z
Reg No. : MR-8500000-9
JBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details

THIRD PARTY CLAIM

Longal

Liability Check

Mr. New Shun

Account No.

S1000020 / TPCLAIM

Document No.

0

Document Date

08/09/2022

Customer Details

Mr Chow Weng Fatt

54 Jalan Riang
Serangoon Park
Singapore 359019

Mobile: 96478122

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
------	-------	---------	-----------	----------	------------	---------	---------------------

2021	AXUH80R	ANXGB 1P	25/08/2021	SFD8688X	0	22035	69DS/SFD8688X
------	---------	----------	------------	----------	---	-------	---------------

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
-------------	------------	-------	--------------	------------	--------------


JTEAD3BH90J000758	A25A0943780	60	Raymond Seah L M	--/--/----	0.00 --/--/----	0.00
-------------------	-------------	----	------------------	------------	-----------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:YN7644B ACC DATE:07/09/2022 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				✓ 30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				✓ 180.00
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.				✓ 122.40
4	B	BP-LAB2 TO REPLACE/REPAIR FRONT LH SIDE ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				✓ 1440 2880.00
5	B	BP-RES2 TO SPRAY PAINT ON FRONT LH SIDE ACCIDENT AFFECTED AREAS.				✓ 1770 2360.00
6	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				✓ 274.77
7	1	T81185-48J10 UNIT, HEADLAMP L	1.00	7067.70		✓ 7067.70
8	2	T52119-4D977 COVER, FR BUMPER	1.00	676.60		✓ 676.60
9	3	T52134-48090 BRACKET, FR BUMPER, L	1.00	173.60		✓ 173.60
10	4	T52536-48080 RETAINER, FR BUMPER L	1.00	108.70		✓ 108.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due



Borneo Motors



TOYOTA

chcops
o. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Chow Weng Fatt 54 Jalan Riang Serangoon Park Singapore 359019 Mobile: 96478122			
			Document No.					
			0					
			Document Date					
			08/09/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	AXUH80R	ANXGB 1P	25/08/2021	SFD8688X	0	22035	69DS/SFD8688X	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEAD3BH90J000758		A25A0943780	60	Raymond Seah L M	---/---/---		0.00 ---/---/---	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
11	5	T90467-05170 CLIP L			2.00	2.80		net 5.60 ✓
12	6	T47749-33030 CLIP, PIN HOLD L			2.00	9.50		un 19.00 ✓
13	7	T53879-33030 RETAINER, FR FENDER L			2.00	13.20		un 26.40 ✓
14	8	T53802-48160 FENDER SUB-ASSY, FR L			1.00	1360.60		2x 1360.60 ✓
15	9	T53828-48060 PROTECTOR, FR FENDER L			1.00	99.30		un 99.30 ✓
16	0	T75362-48080 PLATE, FR FENDER L			1.00	59.10		net 59.10 ✓
Taufik 97495749 WIP 12/9/22 @ 1130 P/P ready before paint 5 days taufik@lkkauto.com					LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			25 days *
Acknowledged by Repairer Signature:								
& on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	15,443.77
Please acknowledge receipt of vehicle			Parts 9,596.60 Labour 5,572.40 Sublet 274.77 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 1,081.06 Less 0.00		Amount Due	16,524.83

Customer Copy