

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ZYX 102112314.

ESTIMATE OF REPAIR

Veh# : SMA7193X

Accident Date : 28/7/22

Location : balestier road

TP Chim.

xiao Tony

Model:

TOYOTA CHR

18/6/2018

3P:

SJJ2269H (CHINA TAIPING)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Delnd</i>	780.10	✓	
2	10pcs	Rear bumper clips <i>new</i>		40.00	✓
3	2pcs	Rear bumper screw clips <i>not a</i>		x	
4	2pcs	Rear o/s & n/s bumper reflector (Accessory) <i>new</i>		600.00	x
5	1pc	Rear bumper lower body kit <i>Delnd</i>		1500.00	700.
6	1pc	Rear bumper diffuser <i>Delnd</i>	520.1	✓ 465	
7	1pc	Rear bumper diffuser tow cover <i>new</i>	80.000	+	
8	1pc	Rear bumper enforcement <i>Dented</i>	580.90	✓ 382	
9	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	145.00	+	
10	2pcs	Rear reverse sensor <i>Delnd</i>		280.00	200
11	1pc	Rear end panel <i>Repair</i>	780.90	+	
12	1pc	Rear end panel inner trim <i>new</i>	378.90	+	
13	4pcs	Rear end panel inner trim clips		20.00	x
14	2pcs	Rear o/s & n/s tail lamp <i>new</i>	1,578.20	+	
15	2pcs	Rear o/s & n/s tail lamp retainer <i>new</i>	168.90	+	
16	2pcs	Rear o/s & n/s tail lamp side garnish	130.00	+	
17	1pc	Rear boot cover <i>Dented</i>	1,517.90	1112	
18	1pc	Rear boot cover weatherstrip <i>at</i>	370.90	✓	
19	1pc	Rear boot cover emblem <i>new</i>	71.70	x	
20	1pc	Rear boot cover 'CHR' emblem <i>new</i>	71.90	x	
21	1pc	Rear boot cover 'HYBRID' emblem <i>new</i>	82.50	x	
22	1pc	Rear boot cover 'Toyota' sticker <i>new</i>	69.80	x	
23	1pc	Rear boot cover inner trim <i>new</i>	890.10	+	
24	11pcs	Rear boot cover inner trim clips <i>new</i>		44.00	x
25	1pc	Rear boot cover lock (Upper) <i>Delnd</i>	770.10	389	
26	1pc	Rear boot cover lock (Lower) <i>new</i>	220.90	x	
27	1pc	Rear boot cover lock switch (Outer) <i>new</i>	380.90	+	
28	1pc	Rear boot cover lock switch (Inner) <i>new</i>	370.90	+	

29	2 pcs	Rear boot cover o/s & n/s reflector <i>new</i>	1,357.80	<i>f</i>		
30	1pc	Rear boot cover keyless sensor (Outer) <i>new</i>		<i>f</i>		
31	2 pcs	Rear o/s & n/s fender wheel guard	240.00	<i>f</i>		
32	6 pcs	Rear o/s & n/s fender wheel guard clips		<i>f</i>		
33	2 pcs	Rear o/s & n/s fender inner trim	1,578.20	<i>f</i>		
34	16 pcs	Rear o/s & n/s fender inner trim clips			64.00	<i>f</i>
35	1 pc	Rear windscreen sealant <i>new</i>			60.00	<i>f</i>
36	1 pc	Rear windscreen moulding <i>new</i>			240.00	<i>165</i>
37	1 pc	Rear top cover compartment	460.00	<i>f</i>		
38	1 pc	Rear spare wheel sponge middle	378.10	<i>f</i>		
39	2pcs	Rear spare wheel o/s & n/s sponge	740.20	<i>f</i>		
40	1 pc	Rear n/s stone guard	378.90	<i>f</i>		
41	1 pc	Rear regn. no. plate			130.00	<i>f</i>
42	1 pc	Rear regn. no. plate bracket			25.00	<i>f</i>
		<i>3499</i> <i>SN: 1165</i> Sub Total:	15,093.80		3003.00	0.00
				25%	0%	10%
		<i>2629.25</i> After Less %:	11,320.35		3003.00	0.00
		Labour				
1		To dismantle damaged parts, straighten & welding.		1,600.00	<i>500</i>	
2		To spray painting.		1,000.00	<i>500</i>	
3		To remove & refit rear exhaust to facilitate repair		100.00	<i>f</i>	
4		To remove & refit rear windscreen, rear seats & roof lining to facilitate repair.		280.00	<i>f</i>	
5		To remove & replace refit reverse sensor camera.		50.00	<i>f</i>	
6		To remove and replace rear tail gate. <i>fittings</i>		80.00	<i>50</i>	
7		To check for fault code and re set electrical system.		180.00	<i>f</i>	
8		To check wiring. <i>1130</i>		100.00	<i>30</i>	
9		To re seal anti rust.		100.00	<i>f</i>	
		Sub Total:		3,490.00		
		Total:		17,813.35		
		After Less 20%:		14,250.68		

Chan

Chan San Choon
 Director
 DipEng, AAE MIMI, MSAE(Aust)

Total: 4919.25
H/S: 39K

Admin G
H/S 12/08/22
04 Days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: