

ESTIMATE OF REPAIR

Veh# SJX7940X

ident Date 14/8/2022

.ocation : 112 TECK WHYE

TP Budget Direct.
Veron.

Model:

TOYOTA VIOS

13/7/2010

3P:

SJQ4462R (AUTO & GENERAL)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>rehd</i>	568.20	<i>486</i>	
2	10 pcs	Front bumper clips <i>re</i>		40.00	
3	1 pc	Front bumper grille (Lower) <i>re</i>	196.20	<i>x</i>	
4	2 pcs	Front bumper o/s & n/s retainer <i>re</i>	182.00	<i>x</i>	
5	1 pc	Front bumper n/s fog lamp garnish <i>re</i>	88.60	<i>x</i>	
6	1 pc	Front grille <i>crush</i>	286.20	<i>✓</i>	
7	4 pcs	Front grille clips <i>re</i>		16.00	<i>✓</i>
8	1 pc	Front emblem <i>re</i>	70.40	<i>✓ 40</i>	
9	1 pc	Front reg. no. plate <i>at</i>		45.00	<i>30</i>
		Sub Total:	1,391.60	101.00	0.00
			25%	0%	10%
		After Less %:	1,043.70	101.00	0.00

	Labour	
1	To dismantle front portion, straighten & welding.	400.00 <i>200</i>
2	To spray painting.	400.00 <i>200</i>
3	To check wiring.	120.00 <i>30</i>
	Sub Total:	920.00
	Total:	2,064.70
	After Less 20%:	1,651.76

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Adrian L
H/s 20/09/22.
02 hrs.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 1125.15
L/S: 900