

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

CHIAN TECK REALTY PTE LTD  
 21 WOODLANDS CLOSE #08-11 PRIMZ  
 BIZHUB  
 SINGAPORE 737854

Contact : 91092822, 94461631

*TP Admin  
 Veron.*

## TAX INVOICE

Repair Code : CLM17360  
 Date in : 06/09/2022  
 Vehicle Num. : YP6740C  
 Model : MITSUBISHI CANTER FEB71ER4SDEC (CBU)  
 Chassis/Eng# : FEB71EA20414/4P10C56363

*10dgs*

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
CABIM PANEL MECHANISM LOCK <i>the new</i>	1	189.90	<del>189.90</del> + 189.90
CABIN PANEL OPENER HANDLE <i>the new</i>	1	276.22	<del>276.22</del> + 276.22
CABIN REAR PANEL <i>Dented</i>	1	1148.40	<del>1,148.40</del> + 1,148.40
CABIN REAR PANEL GLASS WEATHER STRIP <i>new</i>	1	195.75	✓ 195.75
ENGINE MANIFOLD OUTLET PIPE LINES <i>new</i>	1	952.00	<i>3016.30</i> + 952.00
ENGINE OUTLET HOSE <i>2pc</i>	1	117.00	✓ 117.00
ENGINE OUTLET HOSE CASING <i>new</i>	1	259.00	<i>2262.22</i> + 259.00
FRONT DOOR END PILLAR L/R <i>LH Dented</i>	2	1533.24	<i>850</i> <del>3,066.48</del> + 3,066.48
FRONT RH AIR CLEANER DUCT <i>Dented</i>	1	365.10	✓ 365.10
REAR NUMBER PLATE LAMP <i>new</i>	1	200.05	+ 200.05
REAR TAILLAMP L/R <i>LH wt</i>	2	240.05	<i>240.05</i> <del>480.10</del> + 480.10
Subtotal before discount			7,250.00
Percentage discount 25%			1,812.50
<b>Sub-total 1</b>			<b>5,437.50</b>
FLOOR HORIZONTAL WOODEN PANEL <i>A pieces cracked</i>	8	500.00	<i>1600</i> <del>4,000.00</del> + 4,000.00
FLOOR WOODEN CHASSIS MEMBER L/R <i>the new</i>	2	1800.00	<del>3,600.00</del> + 3,600.00
FLOOR WOODEN PANEL <i>the new</i>	1	1200.00	<del>1,200.00</del> + 1,200.00
REAR CABIN FRAME ALUMINIUM PANEL <i>Best</i>	1	600.00	<i>400.</i> <del>600.00</del> + 600.00

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

CHIAN TECK REALTY PTE LTD  
 21 WOODLANDS CLOSE #08-11 PRIMZ  
 BIZHUB  
 SINGAPORE 737854

Contact : 91092822, 94461631

**TAX INVOICE**

Repair Code : CLM17360  
 Date in : 06/09/2022  
 Vehicle Num. : YP6740C  
 Model : MITSUBISHI CANTER FEB71ER4SDEC (CBU)  
 Chassis/Eng# : FEB71EA20414/4P10C56363

REAR CABIN FRAME PANEL	<i>Best</i>	1	1200.00	<del>800</del> <del>1,200.00</del>
REAR CANOPY FRAME	<i>Best.</i>	1	1800.00	<del>1200</del> <del>1,800.00</del>
REAR FENDER ARCH GARNISH L/R	<i>Dehd</i>	2	500.00	<del>800</del> <del>1,000.00</del>
REAR NUMBER PLATE	<i>3 NH</i>	1	25.00	<del>+</del> 25.00
REAR NUMBER PLATE HOLDER	<i>new</i>	1	50.00	<del>+</del> 50.00
REAR NUMBER PLATE PANEL BRACKET	<i>NE new</i>	1	180.00	<del>X</del> 180.00
REAR REVERSE SENSOR - SET	<i>2nd.</i>	1	250.00	<del>20</del> <del>250.00</del>
REAR REVERSE SENSOR BRACKET - SET	<i>2nd</i>	1	80.00	<del>50</del> <del>80.00</del>
REAR STEP BRACKET	<i>Best.</i>	1	800.00	<del>400</del> <del>800.00</del>
REAR TAILGATE	<i>Dented.</i>	1	2700.00	<del>1800</del> <del>2,700.00</del>
REAR TAILGATE '22PAX' STICKER	<i>3 new</i>	1	25.00	<del>15</del> <del>25.00</del>
REAR TAILGATE '60KM/H' STICKER		1	25.00	<del>15</del> <del>25.00</del>
REAR TAILGATE ALUMINIUM CHECKER PANEL	<i>Not new</i>	1	800.00	<del>X</del> 800.00
REAR TAILGATE ALUMINIUM CHECKER PANEL REPAIR KIT	<i>new</i>	1	150.00	<del>80</del> <del>150.00</del>
REAR TAILGATE LOWER PANEL	<i>Rw</i>	1	1100.00	<del>+</del> 1,100.00
REAR TAILGATE OPENER HANDLE L/R	<i>2nd</i>	2	220.00	<del>✓</del> 440.00
REAR UNDER BUMPER	<i>Best</i>	1	1500.00	<del>1000</del> <del>1,500.00</del>
SIDE GATE PANEL L/R	<i>RH Dented</i>	2	2900.00	<del>2200</del> <del>5,800.00</del>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

CHIAN TECK REALTY PTE LTD  
 21 WOODLANDS CLOSE #08-11 PRIMZ  
 BIZHUB  
 SINGAPORE 737854

Contact : 91092822, 94461631

**TAX INVOICE**

Repair Code : CLM17360

Date in : 06/09/2022

Vehicle Num. : YP6740C

Model : MITSUBISHI CANTER FEB71ER4SDEC (CBU)

Chassis/Eng# : FEB71EA20414/4P10C56363

	Subtotal before discount	11000	27,325.00
Percentage discount	0%		0.00
	<b>Sub-total 2</b>		27,325.00
	<b>Parts-total</b>		<b>32,762.50</b>

**LABOUR**

To remove and refit rear windscreen(to FR)	80	120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1200	2,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1100	2,400.00
To apply anti-rust chemical on repaired and replaced panel.	80	120.00
To remove n refix floor carrier deck inorder to replace above item.	450	1,200.00
	<b>Labour Total</b>	<b>5,980.00</b>
	<b>Parts &amp; Labour Total</b>	<b>38,742.50</b>

2990

total: 16252.22  
 H/S: 913K;

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

LKK Auto Consultants hence notify page 3  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

10 Days  
 13K  
 125K  
 10 Days