

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6. #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

**M/S :** CHINA TAIPING INSURANCE (SINGAPORE) PTE  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL: 63896111 FAX: 62247175  
ATTN: Motor Claim Department

**Estimate No:** EST2200289  
**Date:** 07 Sep 2022

**Veh Reg No:** SKA8599B  
**Make/Model:** TOYOTA CAMRY  
HYBRID ASCENT  
SPORT 2.5 CVT  
**Chasis No:** JTNB23HK803071676

**Claim Type:** Third Party  
**Accident Date:** 06/09/2022  
**TP Veh Reg No:** GBH9050E

**Reg. Date:** 01/10/2020  
**Your Ref No:** GBH9050E

## Estimate Repair Cost to Vehicle No :SKA8599B

Quantity	Description	List Price S\$	Amount S\$
<b>List Price</b>			
1	1 PC REAR DOOR RH	1,517.00	
2	1 PC REAR DOOR LOCK RH	667.40	
3	1 PC REAR DOOR RUBBER RH	194.60	
4	1 PC REAR DOOR LOWER RUBBER RH	134.80	
5	1 PC REAR DOOR OUTER CHROME MOULDING RH	222.20	
6	1 PC REAR DOOR FRAME TAPE RH	138.30	
7	1 PC REAR FENDER RH	1,458.20	
		4,332.50	
		Less 25%	1,083.13
			3,249.38
<b>Special Net</b>			
8	1 PC REAR WINDSCREEN GLASS SEALANT	60.00	
9	1 PC REAR WINDSCREEN INNER SEAL RUBBER	60.00	
10	1 SET REAR FENDER TRIM CLIPS R/H	40.00	
		160.00	160.00
<b>Labour</b>			
11	1 TO CHECK WIRING	50.00	
12	1 TO REMOVE AND REFIT REAR DOOR GLASS RH	100.00	
13	1 TO REMOVE AND REFIT REAR DOOR TRIM RH	80.00	
14	1 TO REMOVE AND REFIT REAR CUSHION	200.00	
15	1 TO SPRAY UNDER PANEL SEALANT	120.00	
16	1 TO SPRAY PAINTING	800.00	
17	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00	
18	1 PC TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
		2,770.00	2,770.00

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL: 63896111 FAX: 62247175  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 06/09/2022  
TP Veh Reg No: GBH9050E

Estimate No: **EST2200289**

Date: 07 Sep 2022

Veh Reg No: **SKA8599B**  
Make/Model: TOYOTA CAMRY  
HYBRID ASCENT  
SPORT 2.5 CVT

Chasis No: JTNB23HK803071676

Reg. Date: 01/10/2020

Your Ref No: GBH9050E

## Estimate Repair Cost to Vehicle No :SKA8599B

Quantity	Description	List Price S\$	Amount S\$
		Total	S\$ 6,179.38
		Add GST @ 7%	432.56
		Total Amount Payable	S\$ 6,611.94

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SIX HUNDRED ELEVEN AND CENTS NINETY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE