



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALFRED AUTO SERVICES & SUPPLIES		Ref:	CS/TP22008879/Dcy3e2
BLK 5035 ANG MO KIO 3		Date:	19/09/2022
#01-355 ANG MO KIO INDUSTRIAL PARK 2			
SINGAPORE 569538			
ON BEHALF OF SUSAN CHOO LENG LENG		Code:	TP548
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SLV 3243M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/08/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA CX-5	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6KF2WLAJ0143882	Colour	WHITE
Odometer	46820 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R19	TOYO	5 mm
L/H Front Tyre	225/55 R19	TOYO	5 mm
R/H Rear Tyre	225/55 R19	TOYO	5 mm
L/H Rear Tyre	225/55 R19	TOYO	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/08/2022	Inspection Date	12/08/2022
Survey held at	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 . SINGAPORE 569538		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	