



Main Office : No. 22, Jaian Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0086864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance



TP INSURER:
UNKNOWN

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	31/08/2022
Vehicle Reg. No.:	PD294H	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ V220D, 2.1 D LONG (A)	Vehicle Reg. Date:	05/05/2016
Vehicle Colour:	BLUE	Chassis No:	WDF44781523096942
Engine No:	65195033053872		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	3,859.90
Miscellaneous Items	80.00
Labour	2,470.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,409.90
+ GST 7.00% (S\$)	448.69
Nett Amount (S\$)	6,858.59

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DETAILS

Reference

(Last Synchronised: 07 Sep 2022)

Source:

N/A

MERCEDES-BENZ V220D 2.1 D LONG (A) (Model not available in database)

Parts:

Repairer's

(Price-denominated Standard List)

Labour:

(Unsubmitted, no print-code for PD294H)

Print Code:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILLAMP RH ✓ OR	0.00	0.00	*585.00 F ✓
2	2		*TAILLAMP GROMMET ✓ MK	0.00	0.00	*24.00 F ✓
3	1		*TAILLAMP PANEL ✓ ON MK	0.00	0.00	*230.00 F ✓
4	1		*REAR BOOT LOGO ✓ MK	0.00	0.00	*55.00 F ✓
5	1		*REAR BOOT EMBLEM V220D ✓ NE	0.00	0.00	*60.00 F ✓
6	1		*REAR BOOT EMBLEM C&C ✓ MK	0.00	0.00	*30.00 F ✓
7	1		*REAR BUMPER X R	0.00	0.00	*850.00 F
8	1		*REAR BUMPER SIDE BRACKET RH ? X nn	0.00	0.00	*75.00 F
9	10		*REAR BUMPER CLIPS X	0.00	0.00	*50.00 F
10	1		*REAR FENDER RH ✓ ON	0.00	0.00	*1,550.00 F ✓

F=Franchise part.

Sub Total (\$\$) 3,509.00
+ Margin on L,N Items 10.00% (\$\$) 350.90
Total Parts (\$\$) 3,859.90

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

2534
+10%
2787.40

Estimates on Miscellaneous Items

Particulars

Amount

Particulars	Amount
REAR A/C COOLING UNIT - TO CHECK	-
REAR FENDER INNER PANEL - TO REPAIR	-
REAR SIDE GARNISH - TO CONFIRM	-
REAR SIDE GLASS SEALANT	80.00
Sub Total (S\$)	80.00

40

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO CUT & WELD REAR LAMP PANEL RH, REAR FENDER RH, TO REPAIR REAR INNER PANEL RH, REAR BOOT. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREA	New	800	840.00
2	TO SPRAY AFFECTED AREAS, REAR BOOT, REAR PANEL, REAR BUMPER, REAR FENDER RH & AFFECTED AREAS	New	700	850.00
3	TO REMOVE & REFIX REAR SIDE GLASS RH	New	120	180.00
4	TO REMOVE & REFIX CUSHION & OTHER ATTACHMENT PARTS	New	150	200.00
5	TO REMOVE & REFIX POWER BOOT MOTOR & MECHANISM	New	80	100.00
6	TO DIAGNOSTIC & PROGRAMMING WERE NECESSARY	New	200	250.00
7	TO RUST PROOF AFFECTED AREAS	New	30	50.00
Gross Labour Cost (S\$)				2,470.00

2080

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P/P - 4907.40

Steve (LKK)

20/9/22, 11.00

m n

P/P

L7 B/L

7 dy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: