

Vin's

AUTOMOTIVE GROUP
#V.M.G

Our Ref : TP/202209/C0016
Accident date: 8/9/2022
Your Ref : SJP3861J

Motor Claim Department
China Taiping Insurance (S) Pte Ltd
3 Anson Rd
#16-00 Springleaf Tower
Singapore 079909

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices need to be confirmed
- Third party survey on "Without Prejudice" basis
- No illegal work on 9/9/2022
- Supply necessary materials for the resurveyed and is subject to final approval from Insurance Company

Date: 9/9/2022

Acknowledged by Repairer

Signature:

Date:

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SJP3861J
Model : HONDA STREAM 1.8L A

			Price
1	pc	Rear boot <i>Blue</i>	\$ 991.80
1	pc	Rear boot "Honda" logo <i>X NN</i>	\$ 22.50
1	pc	Rear boot "Stream" logo <i>NGC</i>	\$ 41.70
1	pc	Rear boot plastic garnish <i>X NN</i>	\$ 223.80
1	pc	Rear boot inner trim board <i>BR</i>	\$ 175.30
1	pc	Rear boot rubber <i>Cut</i>	\$ 133.90
1	pc	Rear boot lock <i>Cut</i>	\$ 154.80
1	pc	Rear bumper <i>RL</i>	\$ 674.80
1	pc	Rear bumper tow cover <i>X NN</i>	\$ 13.50
10	pcs	Rear bumper clips @ \$4.2/pc <i>NGC</i>	\$ 42.00
1	pc	Rear end panel <i>X Repair</i>	\$ 346.20
1	pc	Rear end panel garnish <i>RL</i>	\$ 176.90
1	pc	Rear windscreen moulding <i>NGC</i>	\$ 66.80
			\$ 3,064.00
		Less 20%	\$ (612.80)
			\$ 2,451.20

1	pc	Rear Number plate w holder <i>X NN</i>	\$ 40.00
1	pc	Rear bumper reverse sensor <i>DM</i>	\$ 380.00 <i>200</i>
1	pc	Windscreen gum <i>NGC</i>	\$ 80.00 <i>40</i>
		Remove and refix rear windscreen	\$ 180.00 <i>120</i>
		To repair damages	\$ 680.00 <i>400</i>
		To spray painting	\$ 780.00 <i>600</i>
			\$ 4,591.20

VIN'S MOTOR PTE LTD



4 Days.
Wingsm Repair
After repair photos.
Gino Q: ap - 8288282
9/9/2022.