9/16/22, 2:32 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22008900/EVY3M4

Date: 16/09/2022

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00021132201

Claimant Vehicle No :

YL2869M

Insured Vehicle YL9975T

No:

Date of Loss: 31/08/2022 Nature of Claim: TP

Claim No: SNM22D206238/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YL2869M

 Make & Model:
 MITSUBISHI FE639ET0SRDE, 3.9 D (M)
 Engine No:
 4D34J28080

 Reg. Date:
 30/12/2002 (Man. Year: 2002)
 Chassis No:
 FE639EA44037

 Colour:
 White
 Odometer:
 654254 km

Engine Capacity: 3908 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175 R14 Rear Tyre Size: 175 R14
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/09/2022

Date Inspected: 12/09/2022 Inspected At: 33 TUAS BAY

are inspected. T2/09/2022 Inspected At. REPAIRER: TAN LIM MOTOR PTE LTD

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$4,000.00 OMV : \$22,757.00

PARF Rebate (1): \$0

Quota Premium Paid: \$57,140.00 \$752.00 COE Rebate (2): Total Rebate (1) + (2) = : \$752.00

The total amount incurred will be Market Value \$4,000.00 minus Total Rebate \$752.00 = \$3,248.00.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

9/16/22, 2:32 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Sep 2022)

Parts: N/A MITSUBISHI FE639ET0SRDE 3.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YL2869M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

9/16/22, 2:32 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >