



Your Ref : SNM22D206238/C02

Date: 16<sup>th</sup> Sep 2022

Our Ref : CS/CTI22008900/Evy3m4

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YL 2869M  
INSURED VEHICLE: YL 9975T  
ACCIDENT ON 31/08/2022**

Instruction was received to inspect the vehicle Reg. No. YL 2869M. The inspection was conducted on 12/09/2022 at the premises of M/s 33 Tuas Bay, Repairer: Tan Lim Motor Pte Ltd.

The following vehicle information was recorded:


Registration Number	: YL 2869M
Make/Model	: Mitsubishi FE639ET0SRDE
Year of Registration	: 2002
Body Colour	: White
Chassis Number	: FE639EA44037
Engine Capacity	: 3908 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 4,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 752.00)
Nett Liability	<u>S\$ 3,248.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.