

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Nog. No. 155507	198R GST Reg. No. 19-	9007 190-10	
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI22008910/Avy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	te: 18/07/2023	
			Co	de: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SCW 680E	Veh. Inspected	SLR 4178H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10017419/JY	Excess (\$)	0.00	
	Assign From	MAYBIE CHUA	Assign Date	12/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA SIENTA	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	NSP1707041694	Colour	WHITE	
	Odometer	115410 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/70 R15	YOKOHAMA	6 mm	
	L/H Front Tyre	185/70 R15	YOKOHAMA	6 mm	
	R/H Rear Tyre	185/70 R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	185/70 R15	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/09/2022	Inspection Date	12/09/2022	
	Survey held at PREMIUM CARZ SERVICES PTE LTD				
		1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	12)	Estimate Days of Repair			

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: