

Date : 09/09/2022

Veron

NSP1707041694

TO: Auto & General Insurance (Singapore) Pte Ltd
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
Singapore 239924

Our Customer : Cheah Siew Mui

Vehicle No : SLR4178H

Model : Toyota Sienta 1.5G A

Manufacture Year : 2017

Date of Accident : 09/09/2022

Total Estimate Repair Days : 10

Total Pages : 2

Attn : Motor Claim Department

Fax : 6725 0853

Re: Repair Estimate For Third Party Claim against SCW680E

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Del'd</i>	1	\$468.00	\$468.00	✓
2	Rear bumper sponge <i>new</i>	1	\$55.00	\$45.00	+
3	Rear bumper side retainer RH <i>new</i>	1	\$85.00	\$85.00	✓
4	Rear bumper side retainer LH <i>new</i>	1	\$85.00	\$85.00	✓
5	Rear bumper garnish - center <i>Del'd</i>	1	\$241.00	\$241.00	✓
6	Rear bumper center garnish clip <i>new</i>	2	\$10.00	\$20.00	✓
7	Rear bumper side garnish RH <i>Del'd</i>	1	\$162.00	\$162.00	✓
8	Rear bumper side garnish LH <i>new</i>	1	\$162.00	\$162.00	+
9	Rear bumper tow hook cover <i>new</i>	1	\$65.00	\$65.00	+
10	Rear bumper reflector RH <i>new</i>	1	\$84.00	\$84.00	+
11	Tail lamp RH <i>Del'd</i>	1	\$438.00	\$438.00	✓
12	Tail lamp LH <i>new</i>	1	\$438.00	\$438.00	+
13	Tail lamp lower bracket RH <i>Del'd</i>	1	\$76.80	\$76.80	✓
14	Tail lamp lower bracket LH <i>new</i>	1	\$76.80	\$76.80	+
15	Tail lamp lower panel RH <i>new</i>	1	\$245.00	\$245.00	+
16	Tail lamp lower panel LH <i>new</i>	1	\$245.00	\$245.00	+
17	Tail gate <i>Distorted</i>	1	\$1,462.00	\$1,462.00	1248
18	Tail gate sensor <i>Del'd</i>	1	\$254.70	\$254.70	✓
19	Tail gate trimboard <i>Del'd</i>	1	\$235.20	\$235.20	186.
20	Tail gate opening holder <i>Del'd</i>	1	\$124.79	\$124.79	✓
21	Tail gate absorber <i>new</i>	2	280.10	560.20	+
22	Tail gate weatherstrip <i>new</i>	1	\$385.00	\$385.00	✓
23	Tail gate lock <i>Del'd</i>	1	\$398.00	\$398.00	✓
24	Tail gate lower catch <i>new</i>	1	\$58.00	\$58.00	+
25	Tail gate "Toyota" logo <i>new</i>	1	\$78.00	\$78.00	✓
26	Tail gate reflector RH <i>new</i>	1	385.10	385.10	+
27	Tail gate reflector LH <i>new</i>	1	385.10	385.10	+
28	Rear number plate garnish <i>Del'd</i>	1	\$155.00	\$155.00	✓
29	Rear number plate lamp <i>new</i>	2	\$65.40	\$130.80	+
30	Rear end panel - inner <i>new</i>	1	\$890.00	\$890.00	+
31	Rear end panel - outer <i>Del'd</i>	1	\$552.00	\$552.00	✓
32	Rear end panel garnish <i>Del'd</i>	1	\$190.00	\$190.00	✓
33	Wiper Blade <i>new</i>	1	\$48.00	\$48.00	+
34	Wiper Motor <i>Del'd</i>	1	\$255.30	\$255.30	✓
35	Wiper Cover w/arm <i>new</i>	1	\$105.00	\$105.00	+
36	Spare tyre board <i>new</i>	1	\$466.00	\$466.00	+

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
37	Spare tyre panel <i>Reg 5</i>	1	\$704.00	\$704.00	<i>+</i>
38	Rear windscreen w/moulding <i>new</i>	1	\$1,035.00	\$1,035.00 <i>180</i>	<i>150</i>
	Sub Total			\$10,463.39	
	<i>5121.59</i>			Less 25%	
	<i>3844.19</i>			Sub Total 1	
				\$7,847.54	
B.	Spare Parts (S/Nett)				
1	Reverse sensor (set) <i>Dead</i>	1	\$250.00	\$250.00	<i>200</i>
2	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	<i>30</i>
3	Rear end panel garnish clip <i>new</i>	8	\$5.00	\$40.00	<i>20</i>
4	Rear number plate w/casing <i>new</i>	1	\$70.00	\$70.00	<i>x</i>
5	Tail gate trimboard clip <i>new</i>	10	\$5.00	\$50.00	<i>20</i>
6	Reverse camera <i>new</i>	1	\$388.00	\$388.00	<i>x</i>
7	Sealant <i>new</i>	1	\$80.00	\$80.00	<i>60</i>
	Sub-Total 2			\$928.00	
	<i>330</i>				
	Total for Parts			\$8,775.54	
C.	Labour				
1	To check wiring.			\$120.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00	<i>800</i>
3	Spray painting all affected parts & areas.			\$1,400.00	<i>800</i>
4	To spray anti-rust undercoat.			\$120.00	<i>60</i>
5	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00	<i>60</i>
6	To remove and refit tail gate glass.			\$150.00	<i>120</i>
	Total Labour			\$3,240.00	
	<i>1870</i>				
	Total Repair Cost			\$12,015.54	

total: 6241.19 Admin Ls
h/s: 5K h/s 14/09/22
0622yr

Yours faithfully,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Aun Teng
f Premium Carz Services Pte Ltd

acknowledged by Repairer
signature:
date:

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No