

Steve

CS/SPF 22008913/Eg. y3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBF 7755E Yr Regn: 2010/11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha YZF-R15 c.c. 150Colour: Black A/C: Insured / Std / NI / NASp. Reading: 16740 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ME138B016B7033687

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17R: 110/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 7/18/22 D.O.I. 17/9/22Survey held at HKL Lim

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

M/V-6500

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / L.B.J. (\$) _____



HKL LIM TEAM MOTORSPORT PTE LTD

UEN: 202218929Z

Blk 1008 #01-24 Bukit Merah Lane 3, Singapore 159722.
Tel: 6275 6656 Email: hkllimteam@gmail.com

FBF7255E

1	HEAD COWLING / CUT	\$165
2	FRONT SIGNALS LH / CUT	\$66
3	HANDLE BAR RH - BT	\$130
4	HANDLE BAR BALANCER RH - CUT	\$15
5	SIDE MIRROR RH - CUT	\$95
6	STICKER - Ak	\$66
7	GEAR PEDAL - BT	\$77
8	FRONT FOOT REST RH - BT	\$60
9	EXHAUST MUFFLER COVER - CUT	\$77
10	SIDE FAIRING RH - CUT	\$165
11	TOWING	\$40 ✓
12	LABOUR	\$450 280

TOTAL AMOUNT:

\$1,406

Steve (LKK)
12/9/22, 5.00p

m n
L/S
by ALG
3 dgs

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: