



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22008913/Eqy3
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)			Date:	12/09/2022
POLICE LOGISTICS BASE (PLB)				
1 HEMMANT ROADSINGAPORE 438675			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 744J	Veh. Inspected	FBF 7255E	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/054	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	12/09/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/08/2022	Inspection Date	12/09/2022	
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				